

ASSEMBLY TECHNOLOGIES INTL INC -- 484-2, DESOLDERING BRAID, DRI-WICK, (SEE SUPPL) --
3439-00-426-0392

===== Product Identification =====

Product ID:484-2, DESOLDERING BRAID, DRI-WICK, (SEE SUPPL)

MSDS Date:01/13/1999

FSC:3439

NIIN:00-426-0392

Status Code:A

MSDS Number: CLQGL

=== Responsible Party ===

Company Name:ASSEMBLY TECHNOLOGIES INTL INC

Address:1177 WEST MAPLE ROAD

City:CLAWSON

State:MI

ZI

P:48017

Country:US

Info Phone Num:800-550-2510, EXT 112

Emergency Phone Num:248-280-2810 EXT 112

Preparer's Name:VIRGIL BROOKS

CAGE:02105

=== Contractor Identification ===

Company Name:ASSEMBLY TECHNOLOGIES INTL INC

Address:1177 WEST MAPLE ROAD

Box:City:CLAWSON

State:MI

ZIP:48017

Country:US

Phone:800-550-2510, EXT 112

CAGE:02105

===== Composition/Information on Ingredients =====

Ingred Name:PURE COPPER METAL

CAS:7440-50-8

RTECS #:GL5325000

= Wt:99.9

Other REC Limits:1.0 MG/M3

(DUST)
OSHA PEL:1 MG/M3
ACGIH TLV:0.1 MG/M3 (FUME)
EPA Rpt Qty:5000 LBS
DOT Rpt Qty:5000 LBS

Ingred Name:MODIFIED ROSIN
CAS:8050-09-7
RTECS #:VL0480000

===== Hazards Identification =====

Health Hazards Acute and Chronic:SKIN EXPOSURE: POSSIBLE ALLERGIC RASH REACTIONS. EYE CONTACT: POSSIBLE DANGER OF METAL FRAGMENTS. INHALATION: IF PRODUCT IS EXPOSED TO TEMPERATURES IN EXCESS OF 180F, LOCAL VENTILATION MUST BE USED. INGESTION: MAY BE MODERATELY

IRRITATING TO STOMACH LINING. INDUCE VOMITING IF CONSCIOUS. DELAYED EFFECTS: WIRE STRANDS COULD CAUSE INTERNAL DIGESTIVE TRACT BLEEDING. THE 0.1% ROSIN FLUX MAY CAUSE ALL ERGIC REACTIONS, RESULTING IN A SKIN RASH. THE FLUX DOES NOT CONTAIN HAZARDOUS INGREDIENTS.

Explanation of Carcinogenicity:CARCINOGENS: