View NSN Online: https://aerobasegroup.gr/nsn/5910-00-188-1427 GENERAL ELECTRIC CO. CAPACITOR PRO. DEPT. -- 21F807FC -- 5910-00-188-1427 Product ID:21F807FC MSDS Date:01/01/1985 FSC:5910 NIIN:00-188-1427 MSDS Number: BDHHD === Responsible Party === Company Name: GENERAL ELECTRIC CO. CAPACITOR PRO. DEPT. Address: JOHN ST City:HUDSON FALLS State:NY ZIP:12839 Country:US Emergency Phone Num:800-447-4545 CAGE:01002 === Contractor I dentification === Company Name: GENERAL ELECTRIC CO CAPACITOR PRODUCTS DEPARTMENT Address: JOHN ST Box:City:HUDSON FALLS State:NY ZIP:12839 Country:US Phone:518-746-5750 CAGE:01002 ======= Composition/Information on Ingredients ========

Ingred Name: POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)

CAS:1336-36-3

RTECS #:TQ1350000 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

=========== Hazards Identification ================

Effects of Overexposure: ABSORBED THRU SKIN, LUNGS, INTESTI

CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)
======================================
First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR. AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UN CONSCIOUS PERSON VOMIT.
======== Accidental Release Measures ==========
Spill Release Procedures:USE ABSORBENT & DIKES TO PREVENT RUNOFF,ISOLATE & NOTIFY PROPER AUTHORITIES.
======================================
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD Ventilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES,FACE SHIELD Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CON TACT Supplemental Safety and Health OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.
========= Physical/Chemical Properties ==========
HCC:V1 Appearance and Odor:LIGHT STRAW-COLORED LIQUID AROMATIC ODOR
========= Stability and Reactivity Data ==========
STRONG OXIDIZERS
======= Disposal Considerations ==========
Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERA

NE.CAUSES

TURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.