View NSN Online: https://aerobasegroup.gr/nsn/5977-00-247-2656 UNION CARBIDE CORP. -- UCAR ARC CARBONS -- 5977-00-247-2656 Product ID:UCAR ARC CARBONS MSDS Date:01/01/1985 FSC:5977 NIIN:00-247-2656 MSDS Number: BDNLY === Responsible Party === Company Name: UNION CARBIDE CORP. Emergency Phone Num:304-744-3487 CAGE:61637 === Contractor Identification === Company Name: UNION CARBIDE CORP Address:39 OLD RIDGEBURY ROAD Box:City:DAN **BURY** State:CT ZIP:06817-0001 Country:US Phone:800-822-4357/732-563-5522 (MSDS) CAGE:61637 ====== Composition/Information on Ingredients ======== Ingred Name: GRAPHITE, SYNTHETIC CAS:7440-44-0 RTECS #:FF5250100 Fraction by Wt: >95% OSHA PEL:15 MG/M3 TDUST ACGIH TLV:2 MG/M3 TDUST; 9293 ========== Hazards Identification ================ Effects of Overexposure: ELECTRICAL SHOCK FROM ARC CARBONS CAN BE FATAL.FROLONGED BREATHING OF FUMES CAN CAUSE PHEUMOCONIOSIS First Aid:FOR ELECTICAL SHOCK:DISCONNECT POWER.IF VICTIM IS NOT BREATHING START ARTIF.RESP.IMMEDIATELY, PERFERABLE MOUTH TO MOUTH.IF NO PULSE CAN BE FOUND START EXTERNAL HEART MASSAGE AT ONCE.CALL A DR.IMMED.ARC BURNS TO EYES OR SKIN: COLD PACKS-DR. Extinguishing Media: NONBOMBUSTIBLE Unusual Fire/Explosion Hazard: TEMP. OF ARC IS SUCH THAT SURROU

NDING COMBUSTIVLE MATERIALS CAN BE IGNITED.
========= Accidental Release Measures ==========
Spill Release Procedures:FOLLOW GOOD HOUSEKEEPING PRACTICES
======================================
Handling and Storage Precautions:DO NOT HANDLE CARBONS UNTIL COLD AFTER USE IN ARC;DO NOT BREATHE FUMES,DO NOT LOOK AT ARC; DO NOT TOUCH LIVE ELECTRICAL PARTS. Other Precautions:KEEP LAMP CLOSED DURING OPERATION.DO NOT EXPOSE SKIN TO LIGHT RAYS
====== Exposure Controls/Personal Protection ========
Ventilation:LOCAL EXHAUST IS PREFERRED. Eye Protection:LIGHT FILTER NEEDED Supplemental Safety and Health ITEM IS A ENCLOSED ARC CARBON INSIDE OF A LAMP.ARC LIGHT CAN CAUSE EYE & SKIN BURNS.CONTACT WITH HOT ELECTRODES CAN CAUSE SEVERE BURNS.
========= Physical/Chemical Properties =========
HCC:N1 Solubility in Water:NEGLIGIBLE Appearance and Odor:BLACK SOLID OR CORED RODS,NO ODOR.
======================================
Stability Indicator/Materials to Avoid:YES NONE Hazardous Decomposition Products:CO,CO*2,OZONE,OXIDES OF NITROGEN,& CARBON DUST
======== Disposal Considerations ===========
Waste Disposal Methods:INCINERATE OR BURY IN A LANDFILL WHERE PERMITTED UNDER APPREPRIATE FEDERAL,STATE OR LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use

by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.