View NSN Online: https://aerobasegroup.gr/nsn/5970-00-442-0389

Product ID:SCOTCHCAST BRAND RESIN #603 MSDS Date:01/01/1985 FSC:5970 NIIN:00-442-0389 MSDS Number: BDYZJ === Responsible Party === Company Name:3M COMPANY Emergency Phone Num:612-733-2328 CAGE:76381 === Contractor Identification === Company Name: MINNESOTA MINING AND MFG CO, DBA 3M Address:3M CENTER BL DG 224-5S-04 Box:City:SAINT PAUL State:MN ZIP:55144-1000 Country:US Phone:866-556 5712 / 612-733-1110 CAGE:76381 Company Name: MINNESOTA MINING AND MFG CO TELCOMM MARKETS DIV Address:3M AUSTIN CTR Box:City:AUSTIN State:TX ZIP:79769-2963 Country:US Phone:800-426-8688 CAGE:55203

Ingred Name:PHTHALIC ANHYDRIDE (SARA III) CAS:85-44-9 RTECS #:TI3150000 Fraction by Wt: 20% OSHA PEL:2 PPM ACGIH TLV:1 PPM; 9293 EPA Rpt Qty:5000 LBS DO T Rpt Qty:5000 LBS

Ingred Name:4,4'-METHYLENE DIANILINE (SARA III) CAS:101-77-9 RTECS #:BY5425000 Fraction by Wt: 3.0% ACGIH TLV:S; 0.1 PPM; A2; 9192 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB
======================================
Effects of Overexposure:INHALATION OF DUST MAY BE IRRITATING TO RESPIRATORY SYSTEM
======================================
First Aid:EYE CONTACT: FLUSH WITH PLENTY OF WATER. CONSULT A PHYSICIAN SKIN CONTA CT: WASH WITH SOAP & WATER. INHALATION: PROVIDE FRESH AIR
======================================
Extinguishing Media:CARBON DIOXIDE FOAM,DRY CHEMICAL
======================================
Spill Release Procedures: COLLECT SPILLED MATERIAL. CLEAN UP RESIDUE
======================================
 Handling and Storage Precautions: AVOID PROLONGED BREATHING OF DUST, OR PROLONGED OR REPEATED SKIN CONTACT. USE IN WELL VENTILATED AREAS. STORE IN COOL, DRY PLACE. Other Precautions: ELIMINATE SOURCES OF IGNITION INCLUDING WEAK ELECTRICAL SPARKS. GROUND EQUIPMENT.
======== Exposure Controls/Personal Protection ====================================
Respiratory Protection:DUST MASK IF DUSTING OCCURS. Ventilation:LOCAL EXHAUST RECOMMENDED Protective Gloves:RUBBER Eye Protection:GOGGLES Supplemental Safety and Health
======================================
HCC:N1

Spec Gravity:0.1 S

olubility in Water:INSOLUBLE Appearance and Odor:POWDER

Stability Indicator/Materials to Avoid:YES

Waste Disposal Methods: INCINERATE PROPERLY. DO NOT LANDFILL

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner wh atsoever,

expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.