View NSN Online: https://aerobasegroup.gr/nsn/6685-00-684-1495

WEKSLER INSTRUMENTS CORP. -- THERMOMETER, MIL-T-15942; 415-COOG-12BY 6685-00-684-1495

Product ID: THERMOMETER, MIL-T-15942; 415-COOG-12BY MSDS Date:01/01/1987 FSC:6685 NIIN:00-684-1495 MSDS Number: BFLND === Responsible Party === Company Name: WEKSLER INSTRUMENTS CORP. Address:80 MILL RD City:FREEPORT,LONG ISLAND State:NY ZIP:11520-4616 Country:US Info Phone Num :516-623-0100 Emergency Phone Num:516-623-0100 CAGE:64467 === Contractor Identification === Company Name: WEKSLERIGLASS THERMOMETER CORP Address:80 MILL ROAD Box:City:FREEPORT State:NY ZIP:11520 Country:US Phone:516-623-0100 CAGE:64467 Ingred Name:MERCURY (SARA III) CAS:7439-97-6 RTECS #:0V4550000 Fraction by Wt: 100% OSHA PEL:S, C, 0.1 MG/M3 ACGIH TLV:S, 0.05 MG/M3; 9192 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB _____

LD50 LC50 Mixture:TCLO-MAN 4430 UG/CUM 8HR Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: ACUTE MERCURY POISONING IS RARE. MOST OFTEN IT IS THE RESULT OF CHRONIC INHALATION. MERCURY MAY ALSO BE ABSORBED THROUGH THE SKIN. Effects of Overexposure: SIGNS OF MERCURY POISONING ARE: METALLIC TASTE, EXCESSIVE SALIVATION, IRRITABILITY AND TREMORS. SKI N CONTACT MAY CAUSE DERMATITIS AND/OR ALLERGIC SENSITIZATION. Medical Cond Aggravated by Exposure: TUBERCULOSIS, KIDNEY DISEASE, ALCOHOLISM First Aid:REMOVE FROM EXPOSURE. CONSULT A PHYSICIAN. Flash Point:NONE Extinguishing Media: USE MEDIA TO EXTINGUISH SURROUNDING FIRE. Fire Fighting Procedures: USE SELF CONTAINED BREATHING APPARATUS. **Unusual Fire/Exp** losion Hazard: IS NON-FLAMMABLE BUT EVAPORATES RAPIDLY WHEN HEATED, CREATING TOXIC FUMES Spill Release Procedures: VACUUM SPILLS WITH VACUUM HAVING A FILTERED EXHAUST. DO NOT SWEEP. WASH AREA WITH SOAP AND WATER. Neutralizing Agent:NONE Handling and Storage Precautions: HANDLE AND STORE THERMOMETERS CAREFULLY. AVOID BREAKAGE AND RELEASE OF MERCURY. Respiratory Protection: NIOSH APPROVED RESPIRATOR. TYPE DEPENDS ON LEVEL OF EXPOSURE. Ventilation: SUFFICIENT TO MAINTAIN EXPOSURE BELOW TLV. Protective Gloves: RUBBER/PLASTIC Eve Protection:SAFETY GLASSES Other Protective Equipment: CLOTHING NECESSARY TO PREVENT SKIN CONTACT. Work Hygienic Practices: KEEP FOOD STUFF STORED AWAY FROM MERCURY. Supplemental Safety and Health THERMOMETER CONTAINS APPROXIMATELY 1 ML OF MERCURY. THER

E IS NO HAZARD AS LONG AS THE UNIT IS INTACT.

HCC:Z2 Boiling Pt:B.P. Text:676F/358C Melt/Freeze Pt:M.P/F.P Text:-38F/-42C Vapor Pres:0.0019 Vapor Density:1.015 Spec Gravity:13.59 Evaporation Rate & amp; Reference: