

ARDROX URESCO, TRACER TECH DIV -- TRACER TECH D493A DEVELOPER -- 6635-00-703-7406  
===== Product Identification =====

Product ID:TRACER TECH D493A DEVELOPER  
MSDS Date:01/01/1985  
FSC:6635  
NIIN:00-703-7406  
Kit Part:Y  
MSDS Number: BFLZB  
=== Responsible Party ===  
Company Name:ARDROX URESCO, TRACER TECH DIV  
Address:16961 KNOTT AVE  
City:LA MIRADA  
State:CA  
ZIP:90638-6015  
Country:US  
Info Phone Num:714-739-2821  
Emergency Phone Num:714-739-2821  
CAGE:LO834  
=== Contractor Identification ===  
Company Name:ARDROX URESCO, TRACER TECH DIV  
Address:16961 KNOTT AVE  
Box:City:LA MIRADA  
State:CA  
ZIP:90638-6015  
Country:US  
Phone:714-739-2821  
CAGE:LO834  
Company Name:BRENT AMERICA, INC.  
Address:16961 KNOTT AVE.  
Box:City:LA MIRADA  
State:CA  
ZIP:90638-6015  
Country:US  
Phone:714-739-2821  
CAGE:23373

===== Composition/Information on Ingredients =====

Ingred Name:SILICA, CRYSTALLINE - QUARTZ  
CAS:14808-

60-7  
RTECS #:VV7330000  
Fraction by Wt: 100%  
OSHA PEL:SEE TABLE Z3  
ACGIH TLV:0.1 MG/M3 RDUST;9293

===== Hazards Identification =====

Routes of Entry: Inhalation:NO Skin:NO Ingestion:YES  
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:NONE SPECIFIED BY MANUFACTURER.  
Effects of Overexposure:DIRECT CONTACT WITH EYES AND SKIN MAY CAUSE  
SLIGHT TO MILD IRRITATION. IF INVOLVE IN COMBUSTION, MAY PRODUCE  
TOXIC GASES WHICH MAY CAUSE INHALATION PROBLEMS. ACCIDENTAL  
INGESTION OF THE POWDER MAY CAUSE DIARRHEA, VOMITING AND STOMACH  
UPSET.

===== First Aid Measures =====

First Aid:EYE: FLUSH WITH WATER FOR 15 MINUTES WHILE HOLDING EYELIDS  
OPEN. GET MEDICAL ATTENTION. SKIN: WASH WITH SOAP AND WATER. IF  
IRRITATION PERSISTS, GET MEDICAL ATTENTION. INGESTION: IF VICTIM IS  
CONSCIOUS , IMMEDIATELY GIVE 2-4 GLASSES OF WATER, AND INDUCE  
VOMITING. GET MEDICAL ATTENTION.

===== Fire Fighting Measures =====

Flash Point:NONE  
Extinguishing Media:NONE  
Fire Fighting Procedures:NONE  
Unusual Fire/Explosion Hazard:NONE

===== Accidental Release Measures =====

Spill Release Procedures:USE APPROPRIATE PROTECTIVE & SAFETY GEARS.  
SMALL SPILL:SCOOP UP AND PLACE IN DISPOSAL CONTAINER.AVOID CREATING  
DUST. LARGE SPILL:SHOVEL UP POWDER INTO SALVAGE DRUMS.CLEAN SURFACE  
WITH WATER. AVOID CREATING DUST



ith this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.