

SPRAGUE ELEC. CO. -- 200P1900TP1 -- 5910-00-854-7946

=====
Product Identification
=====

Product ID:200P1900TP1

MSDS Date:01/01/1985

FSC:5910

NIIN:00-854-7946

MSDS Number: BFSVT

=== Responsible Party ===

Company Name:SPRAGUE ELEC. CO.

Address:61 SPIT BROOK RD SUITE 305

City:NASHUA

State:NH

ZIP:03060

Country:US

Emergency Phone Num:NONE

CAGE:56289

=== Contractor Identification ===

Company Name:SPRAGU

E ELECTRIC CO WORLD HEADQUARTERS

Address:61 SPIT BROOK RD SUITE 305

Box:City:NASHUA

State:NH

ZIP:03060

Country:US

Phone:603-883-5544/FAX 603-880-1910

CAGE:56289

=====
Composition/Information on Ingredients
=====

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)

CAS:1336-36-3

RTECS #:TQ1350000

EPA Rpt Qty:1 LB

DOT Rpt Qty:1 LB

=====
Hazards Identification
=====

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES
CANC

ER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

=====
First Aid Measures
=====

First Aid:EYES:FLUSH WITH WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR. AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT NO NOT MAKE UNCONSCIOUS PERSON VOMIT.

=====
Accidental Release Measures
=====

Spill Release Procedures:USE ABSORBENT & DIKES TO PREVENT RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.

=====
Handling and Storage
=====

Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS. Other Precautions:LARGE CAPACITORS OF 3 LBS OR MORE PCB REQUIRE LABELS IN STORAGE, USE & TRANSPORTATION

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD
Ventilation:LOCAL EXHAUST
Protective Gloves:RUBBER-IMPERV
Eye Protection:GOGGLES,FACE SHIELD
Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT
Supplemental Safety and Health
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.

=====
Physical/Chemical Properties
=====

HCC:Z3
Appearance and Odor:LIGHT STRAW-COLORED LIQUID AROMATIC ODOR

=====
Stability and Reactivity Data
=====

STRONG OXIDIZERS

=====
Disposal Considerations
=====

=====

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH
TEMPERATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.