View NSN Online: https://aerobasegroup.gr/nsn/6520-01-070-0470

KERR MANUFACTURING COMPANY -- TYTIN, PRECAPSULATED -- 6520-01-070-0470

Product ID:TYTIN, PRECAPSULATED MSDS Date:01/21/1988 FSC:6520 NIIN:01-070-0470 MSDS Number: BGYNR === Responsible Party === Company Name: KERR MANUFACTURING COMPANY Address:28200 WICK ROAD City:ROMULUS State:MI ZIP:48174 Info Phone Num:(313) 946-7800 Emergency Phone Num: (313) 946-7800 CAGE:EO52 9 === Contractor Identification === Company Name: KERR CORP Address:1717 W COLLINS AVENUE Box:City:ORANGE State:CA ZIP:92867-5422 Country:US Phone:800-537-7187 CAGE:33339 Company Name: KERR MANUFACTURING COMPANY, DIVISION OF SYBRON COR Address:28200 WICK ROAD Box:City:ROMULUS State:MI ZIP:48174 Country:US Phone: (313) 946-7800 CAGE:EO529

Ingred Name:MERCURY (SARA III) CAS:7439-97-6 RTECS #:OV4550000 Fraction by Wt: 50% Other RE C Limits:INORGANIC 0.1 MG/CUM OSHA PEL:S, C, 0.1 MG/M3 ACGIH TLV:S, 0.05 MG/M3; 9192 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

LD50 LC50 Mixture:NONE Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:YES Health Hazards Acute and Chronic: EYES/SKIN: MAY CAUSE REDINESS & **IRRITATION. POSSIBLE EYES VISUAL DISTURBANCES & SENSITIZATION** DERMATITIS. INHALATION: MAY CAUSE BRONCHI **OLITIS, PNEUMONITIS** PULMONARY EDEMA. IN NERVOUS IRRITABILITY, WEA KNESS, TREMORS, GINGIVITIS, ERETHISM & GREYING OF LENS OF THE EYE. INGESTION: MAY CAUSE NEUROTOXIC/NEPHROTOXIC EFFECTS. Explanation of Carcinogenicity:NONE Effects of Overexposure: EYES/SKIN: MAY CAUSE REDNESS & IRRITATION. POSSIBLE EYES VISUAL DISTANCES & SENSITIZATION DERMATITIS. INHALATION: MAY CAUSE BRONCHIOLITIS, PNEUMONITIS PULMONARY EDEMA, IN NERVOUS IRRITABILITY, WEAKNES S, TREMORS, GINGIVITIS, ERETH ISM & GREYING OF LENS OF THE EYE. INGESTION: MAY CAUSE

NEUROTOXIC/NEPHROTOXIC EFFECTS.

First Aid:EYE: WASH THROUGHLY W/WATER FOR 15 MIN. HOLDING UPPER & LOWER EYELIDS. CONSULT PHYSICIAN. SKIN: WASH THROUGHLY W/SOAP & WATER. CONSULT PHYSICIAN. INHALATION: REMOVE TO FRESH AIR. CONSULT PHYSICIAN. IN GESTION: CONSULT PHYSICIAN.

Unusual Fire

/Explosion Hazard:HIGH TEMPERATURE INCREASE VAPORIZATION OF THE MERCURY.

Spill Release Procedures:SWEEP UP AS MUCH AS POSSIBLE USING ABSORBENT MATERIAL. VACUUM AREA USING SPECIAL MERCURY VACUUM CLEANER.

Handling and Storage Precautions: WASH HANDS THOROUGHLY W. SOAP & WATER BEFORE EATING, SMOKING, OR USING TOILET FACILITIES. Other Precautions: USIN G ACCORDING TO DIRECTIONS.

Respiratory Protection: WHEN WORKING IN AREAS WHICH EXCEED TLV WEAR DUST MASK W/APPROVED CARTRIDGE FOR MERCURY VAPOR. Ventilation: LOCAL EXHAUST: RECOMMENDED. USE IN A WELL VENTILATED AREA. Protective Gloves: IMPERVIOUS Eve Protection:SAFETY GLASSES Other Protective Equipment: MAY USE LAB COAT/APRON. Work Hygienic Practices: USE GOOD PERSONAL HYGIENE. WASH HANDS THOROUGHLY W/SOAP & WATER BEFORE EA TING, SMOKING/USING TOILET FACILITIES. Supplemental Safety and Health Boiling Pt:B.P. Text:674F Melt/Freeze Pt:M.P/F.P Text:-38F Vapor Pres:>1 Spec Gravity:13.35 Appearance and Odor: BLACKISH GREY ALLOY OF SILVER, TIN & COPPER & ODORLESS. Stability Indicator/Materials to Avoid:YES HALOGENS, NUTRIC ACID

Stability Condition to Avoid:HIGH TEMERATURES

zardous Decomposition Products:MERCURY VAPOR

Waste Disposal Methods:COLLECT SPILLED MATERIAL FOR RECLAMATION USING COMMERCIALLY AVAILABLE MERCURY VAPOR DEPRESSANTS/SPECIALIZED VACUUM CLEANERS. RETURN TO MANUFACTURER.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatso

ever,

expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.