

FIRST BRANDS CORP, REGIONAL OFFICE -- STP GAS TREATMENT -- 6850-01-322-5201

=====
Product Identification
=====

Product ID:STP GAS TREATMENT

MSDS Date:11/03/1986

FSC:6850

NIIN:01-322-5201

MSDS Number: BJXVP

=== Responsible Party ===

Company Name:FIRST BRANDS CORP, REGIONAL OFFICE

Address:17 EXECUTIVE PARK DR NE SUITE 150

City:ATLANTA

State:GA

ZIP:30329

Country:US

Emergency Phone Num:800-822-4357

Pr

Preparer's Name:R. A. OFFERMANN

CAGE:DO273

=== Contractor Identification ===

Company Name:FIRST BRAND CORP., REGIONAL OFFICE

Address:17 EXECUTIVE PARK DR NE SUITE 150

Box:City:ATLANTA

State:GA

ZIP:30329

Country:US

CAGE:0AC35

Company Name:FIRST BRANDS CORP (PHONE:203-728-6194)

Address:88 LONG HILL ST

City:EAST HARTFORD

State:CT

ZIP:06108

Phone:203-731-2300, CHEMTREC 800-424-9300

CAGE:DO273

=====
Composition/Information on Ingredients
=====

Ingredient Name:STODDARD SOLVENT

CAS:8052-4

1-3
RTECS #:WJ8925000
Other REC Limits:NONE SPECIFIED
OSHA PEL:500 PPM
ACGIH TLV:100 PPM; 9293

=====
===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:INGESTION:LITTLE ACUTE TOXICITY.
ASPIRATION INTO LUNGS MAY OCCUR DURING INGESTION, RESULTING IN LUNG
DAMAGE. SKIN:IRRITATION, MODERATE TO SEVERE ON PROLONGED CONTACT.
EYES:MINIMAL
DISCOMFORT. INHALATION:NOSE AND THROAT IRRITATION.
RESPIRATORY IRRITATION.
Effects of Overexposure:INGESTION:NAUSEA AND VOMITING.
INHALATION:DISCOMFORT IN THE NOSE AND THROAT, AND DISCHARGE FROM
THE NOSE. COUGH, CHEST DISCOMFORT, PRODUCTION OF SPUTUM, DIFFICULTY
OF BREATHING, DIZZINESS, WEAKNESS, DIFFICULTY IN WALKING AND COMA.
LIVER AND KIDNEY DEGENERATIVE LESIONS AND DEPRESSION OF BONE MARROW.
SKIN:REDDENING.
Medical Conditions Aggravated by Exposure:DERMATITIS, ASTHMA AND
INFLAMMATORY
OR FIBROTIC PULMONARY DISEASE.

=====
===== First Aid Measures =====

First Aid:INGESTION:DO NOT INDUCE VOMITING. SEEK MEDICAL ATTENTION.
SKIN:REMOVE CONTAMINATED CLOTHING AND WASH SKIN THOROUGHLY WITH
SOAP AND WATER. INHALATION:REMOVE FROM EXPOSURE. GENERAL SUPPORTIVE
MEASURES. SEEK MEDICAL ATTENTION. EYES:IMMEDIATELY FLUSH WITH
PLENTY OF WATER FOR AT LEAST 15 MIN. SEEK MEDICAL ATTENTION.

=====
===== Fire Fighting Measures =====

Flash Point Method:PMCC
Flash Point:110F,43C
Extinguishing Media:WATER FOG, FOAM, ALCOHOL FOAM, CARBON DIOXIDE AND
DRY CHEMICAL.
Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS FOR
CONFINED SPACES. COMBUSTIBLE LIQUID.
Unusual Fire/Explosion Hazard:NONE

=====
===== Accidental Release Measures =====

Spill Release Procedures:WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT
AND REMOVE ALL SOURCES OF IGNITION. COLLECT MATERIAL

