

UNITED RESIN CORPORATION -- HARDENER TP-40 -- 8040-00-944-7292

===== Product Identification =====

Product ID:HARDENER TP-40
MSDS Date:01/01/1987
FSC:8040
NIIN:00-944-7292
Kit Part:Y
MSDS Number: BPPDK
=== Responsible Party ===
Company Name:UNITED RESIN CORPORATION
Address:4359 NORMANDY COURT
City:ROYAL OAK
State:MI
ZIP:48073
Country:US
Info Phone Num:313-549-8200
Emergency Phone Num:313-549-8200
Preparer's Name:RICHARD J ELLER
CAGE:1FD35
=== Contractor Identification ===
Company Name:UNITED RESIN CORPORATION
Address:4359 NORMANDY COURT
City:ROYAL OAK
State:MI
ZIP:48073
Country:US
Phone:248-549-8200/
CAGE:1FD35

===== Composition/Information on Ingredients =====

Ingred Name:SAFETY ADDUCTED MODIFIED POLYAMINE EPOXY CURING AGENT
CAS:68610-56-0
Other REC Limits:NONE SPECIFIED

===== Hazards Identification =====

Health Hazards Acute and C

hronic:STRONGLY IRRITATING TO SKIN AND EYES.

=====
First Aid Measures
=====

First Aid:DO NOT ALLOW TO CONTACT SKIN OR EYES; WASH IMMEDIATELY, AND LAUNDER BEFORE REUSING.

=====
Fire Fighting Measures
=====

Flash Point Method:TOC

Flash Point:175F,79C

Extinguishing Media:WATER SPRAY, CO2, DRY CHEMICAL

Fire Fighting Procedures:NO SPECIAL PROCEDURES--AVOID INHALATION OF SMOKE

Unusual Fire/Explosion Hazard:NO UNUSUAL HAZARDS

=====
Accidental Release Measures
=====

Spill Release Procedures:CLEAN WITH A CLOTH OR ABSORBENT PAPER, FLUSH REMAINDER WITH LARGE AMOUNT OF WATER.

=====
Handling and Storage
=====

Handling and Storage Precautions:STORE IN A COOL PLACE.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:ORGANIC CANNISTER MASK

Ventilation:LOCAL EXHAUST: HIGHLY RECOMMENDED. MECHANICAL (GENERAL): HIGHLY RECOMMENDED.

Protective Gloves:RUBBER

Eye Protection:CHEMICAL GOGGLES.

Other Protective Equipment:AS REQUIRED TO PREVENT ALL BODY CONTACT.

Supplemental Safety and Health

=====
Physical/Chemical Properties
=====

Vapor Pres:1

Spec Gravity:1.095

Solubility in Water:SLIGHTLY

Appearance and Odor:LIQUID, AMINE ODOR.

=====
Stability and Reactivity Data
=====

Stability Indicator/Materials to Avoid:YES

STRONG OXIDIZING AGENTS--COPPER OR

COPPER ALLOYS

Hazardous Decomposition Products:CARBON MONOXIDE, ALDEHYDES, AND OTHER ORGANICS

Conditions to Avoid Polymerization:EXOTHERMS WHEN USED TO CURE RESINS

===== Disposal Considerations =====

Waste Disposal Methods:CONTROLLED BURNING OR BURIAL IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of D

efense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.