View NSN Online: https://aerobasegroup.gr/nsn/6510-01-216-6073 CLINIPAD CORP -- POVIDONE IODINE SOLUTION;9153 -- 6510-01-216-6073 Product ID:POVIDONE IODINE SOLUTION;9153 MSDS Date:09/19/1990 FSC:6510 NIIN:01-216-6073 MSDS Number: BVZKJ === Responsible Party === Company Name: CLINIPAD CORP Address:66 HIGH ST Box:387 City:GUILFORD State:CT ZIP:06437-3445 Country:US

Info Phone Num:203-453-6543 FAX:203-458-9526

Emergency Phone Num:203-453-6543

Preparer's Name:L.P.MARTIN

CAGE:58574

=== Contractor Identification === Company Name: CLINIPAD CORP Address:175 CAPITAL BLVD

Box:City:ROCKY HILL

State:CT ZIP:06067 Country:US

Phone:860-571-0100

CAGE:58574

======= Composition/Information on Ingredients ========

Ingred Name:BETADINE (PROVIDONE-IODINE)

CAS:25655-41-8 RTECS #:TR1579600

Other REC Limits: NONE RECOMMENDED

============ Hazards Identification =========================

LD50 LC50 Mixture: ORAL LD50 (R

AT) IS >8GM/KG
Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:POVIDONE-IODINE IS DERMALLY
ABSORBED; CHRONIC EXPOSURE MAY INDUCE HYPERTHYROIDISM.
Explanation of Carcinogenicity:THERE ARE NO INGREDIENTS ABOVE 0.1% WHICH ARE IDENTIFIED AS CARCINOGENS BY NTP,IARC OR OSHA.
Effects of Overexposure:HYPERTHROIDISM(THYROTOXICOSIS)-RAPID HEARTBEAT,SWEATING,ANXIETY,INCREASED APPETITE,WEIGHT LOSS,INTO
LERANCE OF HEAT.
Medical Cond Aggravated by Exposure:PERSONS WITH PRE-EXISTING THYROID AILMENTS MAY BE AT INCREASED RISK FROM EXPOSURE.
======================================
First Aid:SKIN:DISCONTINUE USE;REMOVE CONTAMINATED CLOTHING;WASH WITH WATER.EYES:FLUSH WITH WATER FOR 15 MINUTES.INHAL:UNLIKELY ROUTE OF EXPOSURE.INGEST:DO NOT INDUCE VOMITING.GET PROMPT QUALIFIED MEDICAL ATTEN TION.
======================================
Flash Point:NONE Extinguishing Media:WATER FOG,DRY CHEMICAL,FOAM. Fire Fighting Procedures:USE A SELF-CONTAINED BREATHING APPARATUS AND FULL PROTECTIVE EQUIPMENT. Unusual Fire/Explosion Hazard:NONE SPECIFIED BY MANUFACTURER.
========= Accidental Release Measures ==========
Spill Release Procedures:DILUTE WITH WATER;SOAK UP WITH NON-COMBUSTIBLE INERT ADSORBANT(EG.CLAY);PLACE COLLECTED MATERIAL IN AN APPROPRIATE CONTAINER FOR DISPOSAL;CLEAN SPILL AREA TO REMOVE SLIPPERINESS. Neutralizing Agent:NONE
======================================
Handling and Storage Precautions:STORE IN A COOL,DRY,WELL-VENTILATED PLACE.KEEP CONTAINER CLOSED WHEN NOT IN USE. Other Precautions:AVOID SKIN AND EYE CONTACT.DO NOT INGEST;FOR EXTERNAL USE ONLY.
====== Exposure Controls/Personal Protection =======
Respiratory Protection:NOT NEEDED IN NORMAL SERVICE. Ventilation:USE GENERAL DILUTION VENTILATION. Protective

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH FEDERAL,STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this informat ion by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.