

HARRIS CORP R F COMMUNICATIONS DIV -- 755017A4800 TUNE DETECTOR ASSEMBLY. (AN ARTICLE) -- 5998-01-047-9166

=====
Product Identification
=====

Product ID:755017A4800 TUNE DETECTOR ASSEMBLY. (AN ARTICLE)

MSDS Date:06/21/1995

FSC:5998

NIIN:01-047-9166

MSDS Number: BXVQP

=== Responsible Party ===

Company Name:HARRIS CORP R F COMMUNICATIONS DIV

Address:1680 UNIVERSITY AVE

City:ROCHESTER

State:NY

ZIP:14

610-1839

Country:US

Info Phone Num:716-244-5830

Emergency Phone Num:716-244-5830

Preparer's Name:WILLIAM L. JACKSON

CAGE:14304

=== Contractor Identification ===

Company Name:HARRIS CORP R F COMMUNICATIONS GROUP

Address:1680 UNIVERSITY AVE

Box:City:ROCHESTER

State:NY

ZIP:14610-1839

Country:US

Phone:716-244-5830

CAGE:14304

=====
Composition/Information on Ingredients
=====

Ingred Name:THERE ARE NO HAZARDOUS MATERIALS IN THIS ASSEMBLY.

Fraction by Wt: 100%

Other REC Limits:NONE

RECOMMENDED

=====
Hazards Identification
=====

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:NONE SPECIFIED BY MANUFACTURER.

Explanation of Carcinogenicity:NONE

=====
Fire Fighting Measures
=====

Flash Point:NONE

Lower Limits:NONE

Upper Limits:NONE

Extinguishing Media:USE MEDIA APPROPRIATE FOR SURROUNDING MATERIAL.

Fire Fighting Proc

cedures:USE PROCEDURES APPROPRIATE FOR SURROUNDING
FIRE.

Unusual Fire/Explosion Hazard:NONE.

===== Accidental Release Measures =====

Spill Release Procedures:NONE REQUIRED.

Neutralizing Agent:NONE.

===== Handling and Storage =====

Handling and Storage Precautions:HANDLE AND STORE PER PRECAUTIONS FOR
EQUIPMENT CONTAINING COMMON ELECTRONIC COMPONENTS.

Other Precautions:NONE SPECIFIED BY MANUFACTURER.

===== Exposure
Controls/Personal Protection =====

Respiratory Protection:NONE REQUIRED.

Ventilation:NORMAL VENTILATION FOR AREAS CONTAINING EQUIPMENT
CONSISTING OF COMMON ELECTRONIC COMPONENTS.

Protective Gloves:NONE REQUIRED.

Eye Protection:NONE REQUIRED.

Other Protective Equipment:NONE REQUIRED.

Work Hygienic Practices:NORMAL WORKPLACE HYGENIC PRACTICES ARE
ADEQUATE.

Supplemental Safety and Health
MANUFACTURER DOES NOT ISSUE MSDS FOR ASSEMBLIES. INSTEAD THEY WOULD
PERFORM A SAFETY HAZA
RD ANALYSIS AND SAFETY ASSESSMENT ON THE
EQUIPMENT WHICH WOULD IDENTIFY ALL HAZARDS. REQUEST FOR TASKS OF
THIS LEVEL ARE MADE AS PART OF A CONTRACT. FURTHER REQUESTS MUST
BE FORWARDED IN WRITING,TO ALLOW REVIEW OF SCOPE OF REQUEST.

===== Physical/Chemical Properties =====

HCC:N1

Appearance and Odor:AN ASSEMBLY.

Percent Volatiles by Volume:NONE

Corrosion Rate:NONE

===== Stability and Reactivity Data =====

Stability Indicator/M

aterials to Avoid:YES

NONE SPECIFIED BY MANUFACTURER.

Stability Condition to Avoid:NONE SPECIFIED BY MANUFACTURER.

Hazardous Decomposition Products:NONE SPECIFIED BY MANUFACTURER.

===== Disposal Considerations =====

Waste Disposal Methods:MANUFACTURER RECOMMENDS FOLLOWING EPA,STATE,AND LOCAL REGULATIONS.THE TUNE DETECTOR ASSEMBLY DOES NOT CONTAIN MERCURY,PCB'S,OTHER CARCINOGENIC MATERIALS.THERE ARE NO HAZARDOUS MATERIALS IN THE ASSEMBLY,EXCEPT FOR INSIGNIFICANT AMOUNT OF LEAD SOLDER.

=====

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.