

OEA AEROSPACE INC. -- 51323-1 CONNECTOR,TRANSFER,EXPLOSIVE ASSEMBLY --
1377-01-243-0321

===== Product Identification =====

Product ID:51323-1 CONNECTOR,TRANSFER,EXPLOSIVE ASSEMBLY

MSDS Date:01/12/1996

FSC:1377

NIIN:01-243-0321

MSDS Number: CCGLV

=== Responsible Party ===

Company Name:OEA AEROSPACE INC.

Address:HWY 12 AND ET RD

Box:KK

City:FAIRFIELD

State:CA

ZIP:94533-0659

Country:US

Info Phone Num

:707-422-1880

Emergency Phone Num:707-422-1880

Preparer's Name:S SCHOOLFIELD/J KOHRING

CAGE:17610

=== Contractor Identification ===

Company Name:OEA AEROSPACE INC

Address:3530 BRANSCOMBE RD

Box:KK

City:FAIRFIELD

State:CA

ZIP:94533-0659

Country:US

Phone:707-422-1880

CAGE:17610

===== Composition/Information on Ingredients =====

Ingred Name:HEXANITROSTILBENE I

Ingred Name:HEXANITROSTILBENE II

===== Hazards Identification =====

Routes of Entry

: Inhalation:YES Skin:NO Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:INHALATION: IRRITATION TO THE NOSE,
THROAT, MUCOUS MEMBRANE & ALLERGIC REACTIONS. SKIN: IRRITATION &
POSSIBLE ALLERGIC REACTIONS. EYES: IRRITATION. INGESTION: TOXIC.
Explanation of Carcinogenicity:NONE
Effects of Overexposure:IRRITATION, NAUSEA, REDNESS.

=====
===== First Aid Measures =====

First Aid:EYES: FLUSH W/WATER FOR 15 MI
NS. SKIN: WASH W/SOAP & WATER.
INHALATION: REMOVE TO FRESH AIR. OBTAIN MEDICAL ATTENTION IN ALL
CASES.

=====
===== Fire Fighting Measures =====

Extinguishing Media:DON'T ATTEMPT TO EXTINGUISH.
Fire Fighting Procedures:EVACUATE AREA. USE SCBA TO CONTAIN RESULTING
FIRE.
Unusual Fire/Explosion Hazard:IF EXPOSED TO FIRE, THE UNIT MAY
ACTUATE/EXPLODE.

=====
===== Accidental Release Measures =====

Spill Release Procedures:CALL LOCAL
HAZARDOUS MATERIALS TEAM. REMOVE
IGNITION SOURCES. COVER/EXPOSED MATERIAL W/VEGETABLE OIL & REMOVE
FOR APPROVED DISPOSAL.

=====
===== Handling and Storage =====

Handling and Storage Precautions:DON'T STORE AT TEMPS >200F.
Other Precautions:ANTI-STATIC BAGS SHALL BE USED FOR STORAGE &
SHIPPING.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE NIOSH APPROVED HEPA RESPIRATOR IF PEL/TLV IS
EXCEEDED.

Venti

lation:LOCAL EXHAUST: REQUIRED FOR TEST FIRING.
Protective Gloves:POLY-BENZ-IMMIDAZOLE/LEATHER
Eye Protection:SAFETY GLASSES AS A MINIMUM
Other Protective Equipment:FLAME RETARDANT COAT & GROUNDING STRAPS TO
PREVENT ELECTROSTATIC DISCHARGE.
Supplemental Safety and Health

===== Physical/Chemical Properties =====

Solubility in Water:LOW
Appearance and Odor:HNS: YELLOW POWDER; ODORLESS

===== Stability and Reactivity Data =====

Stability

Indicator/Materials to Avoid:YES
ALKALIS, ACIDS, COPPER, BRONZE, CORROSIVES & OXIDIZERS, WATER.
Stability Condition to Avoid:MECHANICAL SHOCK, STATIC ELECTRICITY,
HEAT, FLAME/SPARKS.
Hazardous Decomposition Products:CO, NITROGEN, NITROUS OXIDES,
HYDROGEN, CARBON, CO2.

===== Disposal Considerations =====

Waste Disposal Methods:UNFIRED UNITS/WASTE SHOULD BE DISPOSED AS
REACTIVE HAZARDOUS WASTE, D003 IAW/FEDERAL, STATE & LOCAL
REGULATIONS. UN 0367.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.