

EMERSON CUMING INC. SUB OF W R GRACE AND CO. -- STYCASET 2651 -- 5970-00-208-8070

===== Product Identification =====

Product ID:STYCASET 2651

MSDS Date:03/11/1997

FSC:5970

NIIN:00-208-8070

Kit Part:Y

MSDS Number: CGLRD

=== Responsible Party ===

Company Name:EMERSON CUMING INC. SUB OF W R GRACE AND CO.

Address:77 DRAGON COURT

City:WOBURN

State:MA

ZIP:01888

Country:US

Info Phone Num:617-828-3300

Emergency Phone Num:617-935-4850/617-938-8630

Preparer's Name:DAVID

HAAS

CAGE:0B562

=== Contractor Identification ===

Company Name:EMERSON & CUMING

Address:55 HAYDEN AVE

Box:City:LEXINGTON

State:MA

ZIP:02173

Country:US

Phone:617-861-6600

CAGE:0B562

===== Composition/Information on Ingredients =====

Ingred Name:EPOXY RESIN

Fraction by Wt: 40-50%

Other REC Limits:NONE RECOMMENDED

Ingred Name:SILICA, CRYSTALLINE

Fraction by Wt: 20-30%

Other REC Limits:NONE RECOMMENDED

Ingred Name:MICA

Fraction by Wt: 20-30%

Other REC Limits:NONE RECOMMENDED

Ingred Name:PHENYL GLYCIDYL ETHER (PGE)

CAS:122-60-1

RTECS #:TZ3675000

Fraction by Wt: 2-5%

Other REC Limits:NONE RECOMMENDED

OSHA PEL:10 PPM

ACGIH TLV:S, 1 PPM; A3; 9596

Ingred Name:CARBON BLACK

CAS:1333-86-4

RTECS #:FF5800000

Fraction by Wt: 200F,>93C

Autoignition Temp:Autoignition Temp Text:NP

Lower Limits:N/ESTABLISH

Upper Limits:N/ESTABLISH

Extinguishing Media:USE CARBON DIOXIDE, DRY CHEMICAL,FOAM,WATER FOG.

Fire Fighting Procedures:FIREFIGHTER/RESCUE PERSONNEL SHOULD WEAR

+PRESS SCBA

& FULL PROT EQPMT.COOL EXPO CNTNR W/H2O TO PREVENT

PRESSURE BUILDUP.LG QUANT OF MATLS INVOLVE EVACUATE(SUP)

Unusual Fire/Explosion Hazard:DECOMPOSITION AND COMBUSTION PRODUCTS MAY  
BE TOXIC.CLOSED CNTNRS MAY VIOLENTLY RUPTURE UNDER FIRE CONDITIONS.

===== Accidental Release Measures =====

Spill Release Procedures:CONDUCT RESPONSE OPERATIONS IAW PROVISIONS OF  
29CFR1910.120.REVIEW WHOLE MSDS BEF PROCEEDING.SM-ACTIVATE EXHAU  
VENTI.WIPEUP/ABSORB W/VERMI/SI

MILAR MATL.WASH AREA W/SOAPY

H2O-REMOVES RESIDUE.COLLECT MA TL/RINSE IN APPROP CNTNR.DISPO IAW  
ALL (SUPPLEME)

Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER.

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL DRY LOC W/ADEQU  
VENTI.KEEP CNTNR TIGHTLY SEAL WHEN NOT IN USE.KEEP AWAY FRM  
FLAME/HEAT SOURCE.CONSULT PROD TECH BULLETIN FOR STORAGE INF

Other Precautions:BECAUSE OF USAGE CONDITIONS WILL VARY DEPENDING ON  
CUSTOMER APPLICATION SPEC SAF HNDLG PROCEDURES SHOULD BE DEVLP BY  
PERSON KNOWLEDGEABLE IN INTENDED USAGE CONDITIONS/EQPMT.WORKER MUST  
BE PROPERLY TRA IN IN SAF HNDLG OF PROD PRIOR TO USE.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE APROPRIATE PROPERLY FITTED RESP IF EXPO  
EXCEED PEL/TLV VALUES.TYP SELECTED WILL DEPEND ON CONDITIONS OF  
USE.OBSERVE OSHA REGS FOR RESP PROT(29CFR1910.134).

Ventilation:PROVIDE EFFECTIVE MECH EXHA

U VENTI-DRAW VAP/MIST/FUME FRM

PROCESS AWAY FRM WORK/PREVENT INHAL,ESPEC @HI TEMPS.

Protective Gloves:APPROPRIATE PROTECTIVE GLOVES

Eye Protection:FCSHIELD,SPLASH PRO CHEM GOG,CHEM SAF GL

Other Protective Equipment:PROPER CHEM RESIST APRON,ADDN IMPERV  
CLOTH.EMERG EYE WASH/SAF SHOWER.

Work Hygienic Practices:NORMAL WORK CLOTH SHOULD BE WASH BEF REUSE.WASH  
HAND/FC WELL AFT HNDLG/BEF EAT/DRINK/SMOKE.

Supplemental Safety and Health

KEY1:N1. FIREFIGHTER:AREA,FIGHT FIRE FRM SAFE DISTANCE.

DECOMPO:BYPRODUCTS VARY WIDELY DEPENDING ON CONDITIONS OF  
COMBUSTION. SPILL:REGS.LG-LIMIT ACCESS.SHUT OFF SOURCE W/O

RISK.ACTIVATE EXHAU VETN.D IKE/CONTAIN/PREVENT RELEASE TO

SEWER/DRAIN/H2OWAYS.COLLECT FOR SALV/DISPO.SOAKUP W/ABSORBENT.WASH  
W/SOAPY H2O.

===== Physical/Chemical Properties =====

HCC:B2

Boiling Pt:B.P. Text:ND

Melt/Freeze Pt:M.P/F.P Text:NP

Decomp Temp:Decomp Text:NP

Vapor Pres:NELGIGIBLE

Vapor Density:>AIR

Spec Gravity:1.65

pH:NP

Viscosity:NP

Evaporation Rate & Reference:NP

Solubility in Water:INSOLUBLE

Appearance and Odor:BLACK LIQUID

Percent Volatiles by Volume:2.5

Corrosion Rate:NP

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

INCOMPATIBLE W/STRONG OXIDIZERS,ACIDS,BASES,UNCONTROLLED MIX  
W/AMINES,ANHYDRIDES,MERCAPTANS,IMIDZOLES MAY CAUSE HAZ POLY

Stability Condition to Avoid:AVOID STORAGE IN OPN CNTNR,EXPO TO OPN  
FLAME/UNCNTRLD EXPO TO HEAT,

UNCNTRLD MIXING W/CURE AGENTS,EXPO TO  
INCOMPAT SUBSTS

Hazardous Decomposition Products:FUMES/VAPORS FROM THERM/CHEM  
DECOMPOSITIONS MAY VARY WIDELY IN COMPOSITION AND TOXICITY.  
Conditions to Avoid Polymerization:REVIEW REACTIVITY DATA CONCERNING  
CONDITIONS TO AVOID AND INCOMPATIBLE SUBSTANCES.

===== Disposal Considerations =====

Waste Disposal Methods:NO SARA SEC 313 SUBSTANCES.DISPOSE OF IAW  
CURRENT LOCAL, STATE AND FEDERAL REGULATIONS.

Disclai  
mer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify and  
assume responsibility for the suitability of this information to their  
particular situation.