View NSN Online: https://aerobasegroup.com/nsn/8030-00-830-1821

CIBA-GEIGY CORP FORMULATED SYSTEMS GROUP -- RP 1250 RESIN, PART A -- 8030-00-830-1821

Product ID:RP 1250 RESIN, PART A

MSDS Date:11/07/1996

FSC:8030

NIIN:00-830-1821

Kit Part:Y

MSDS Number: CGXBZ === Responsible Party ===

Company Name: CIBA-GEIGY CORP FORMULATED SYSTEMS GROUP

Address:4917 DAWN AVENUE

City: EAST LANSING

State:MI ZIP:48823

Info Phone Num: (517) 351-5

900

Emergency Phone Num:(517) 351-5900 Preparer's Name:MICHAEL L. MUNSELL

CAGE:02684

=== Contractor Identification ===

Company Name: CIBA SPECIALTY CHEMICALS CORPORATION

Address:4917 DAWN AVE Box:City:EAST LANSING

State:MI

ZIP:48823-5691 Country:US

Phone:517-351-5900

CAGE:02684

======= Composition/Information on Ingredients ========

Ingred Name: ALUMINUM (SARA 313)

CAS:7429-90-5

RTECS #:BD0330000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:15 MG/M3 DUST

ACGIH TLV:10 MG/M3 DUST; 9596

Ingred Name: BISPHENOL A

CAS:80-05-7

RTECS #:SL6300000

Other REC Limits: NONE RECOMMENDED

Ingred Name: DIETHYLENETRIAMINE

CAS:111-40-0

RTECS #:IE1225000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:1 PPM

ACGIH TLV:S, 1 PPM; 9596

Ingred Name:TRIETHYLENE TETRAMINE

CAS:112-24-3

RTECS #:YE6650000

Other REC Limits: NONE RECOMMENDED

Ingred Name: CALCIUM CARBONATE (MARBLE) (LIMESTONE)

CAS:1317-65-3

RTECS #:EV9580000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9596

Ingred Name: SILICA, FUMED.

CAS:7631-86-9

Other REC Limits: NONE RECOMMENDED

Ingred Name: ALUMINUM HYDROXIDE

CAS:21645-51-2 RTECS #:BD0940000

Other REC Limits: NONE RECOMMENDED

Ingred Name: NONYLPHENOL

CAS:25154-52-3

RTECS #:SM5600000

Other REC Limits: NONE RECOMMENDED

Ingred Name: POLYAMIDE RESIN

CAS:68410-23-1

Other REC Limits: NONE RECOMMENDED

Ingred Name: 1,3 BENZENEDIMETHANAMINE, POLY W/2,2'-(1-METHYLETHYLIDENE)

BIS (4,1-PHENYLENEOXYMETHTLENE) BIS (OXIRANE) & OTHERS

CAS:68738-77-2

Other REC

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:SKIN IRRITATION. EYE IRRITATION. Explanation of Carcinogenicity:NONE Effects of Overexposure:CORROSIVE. CAUSES EYE BURNS AND SKIN IRRITATION. CAUSES ALLERGIC SKIN AND RESPIRATORY REACYIONS. Medical Cond Aggravated by Exposure:SKIN AND EYE CONDITIONS. ====== First Aid:EYES-IMMEDIATELY FLUSH WITH WATER FOR 15 MIN. CALL A PHYSICIAN. SKIN-WASH WITH SOAP AND WATER. REMOVE CONTAMINATED CLOTHES & LAUNDER BEFORE RESUE. INGESTION-IF CONSCIOUS, GIVE PLENTY OF WATER TO DRINK. DO NOT INDUCE VOMITING. CALL A PHYSICIAN. INHALATION-REMOVE TO FRESH AIR. GIVE OXYGEN &/OR ARTIFICIAL RESPIRATION, IF NEEDED. CALL A PHYSICIAN.
First Aid:EYES-IMMEDIATELY FLUSH WITH WATER FOR 15 MIN. CALL A PHYSICIAN. SKIN-WASH WITH SOAP AND WATER. REMOVE CONTAMINATED CLOTHES & LAUNDER BEFORE RESUE. INGESTION-IF CONSCIOUS, GIVE PLENTY OF WATER TO DRINK. DO NOT INDUCE VOMITING. CALL A PHYSICIAN. INHALATION-REMOVE TO FRESH AIR. GIVE OXYGEN &/OR ARTIFICIAL
First Aid:EYES-IMMEDIATELY FLUSH WITH WATER FOR 15 MIN. CALL A PHYSICIAN. SKIN-WASH WITH SOAP AND WATER. REMOVE CONTAMINATED CLOTHES & LAUNDER BEFORE RESUE. INGESTION-IF CONSCIOUS, GIVE PLENTY OF WATER TO DRINK. DO NOT INDUCE VOMITING. CALL A PHYSICIAN. INHALATION-REMOVE TO FRESH AIR. GIVE OXYGEN &/OR ARTIFICIAL
PHYSICIAN. SKIN-WASH WITH SOAP AND WATER. REMOVE CONTAMINATED CLOTHES & LAUNDER BEFORE RESUE. INGESTION-IF CONSCIOUS, GIVE PLENTY OF WATER TO DRINK. DO NOT INDUCE VOMITING. CALL A PHYSICIAN. INHALATION-REMOVE TO FRESH AIR. GIVE OXYGEN &/OR ARTIFICIAL
======================================
Flash Point:>200F,>93C Extinguishing Media:DRY CHEMICAL, CARBON DIOXIDE, FOAM Fire Fighting Procedures:USE SELF CONTAINED BREATHING APPARATUS Unusual Fire/Explosion Hazard:DECOMPOSITION AND COMBUSTION PRODUCTS MAY BE TOXIC.
========= Accidental Release Measures ===========
Spill Release Procedures:REMOVE SPILLAGE BY ABSORBING IN ABSORBENT MATERIAL. Neutralizing Agent:NONE.
======================================
Handling and St

Limits:NONE RECOMMENDED

orage Precautions: KEEP CONTAINER CLOSED. USE WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING. AVOID BREATHING VAPOR OR MIST. Other Precautions: DANGER! CORROSIVE-CAUSES EYE BURNS AND SKIN IRRITATION. HARMFUL IF ABSORBED THROUGH SKIN. DO NOT GET IN EYES. AVOID CONTACT WITH SKIN AND CLOTHING. ====== Exposure Controls/Personal Protection ======== Respiratory Protection: USE AMINE ORGANIC CARTRIDGE VAPOR RESPIRATOR, IF NEEDED. Ventilation: GENERAL MECHANICA L AND LOCAL EXHAUST IN ACCORDANCE WITH ACGIH RECOMMENDATIONS. Protective Gloves: WEAR IMPERMEABLE GLOVES. Eye Protection: WEAR SPLASH PROOF CHEMICAL GOGGLES. Other Protective Equipment: NONE SPECIFIED BY MANUFACTURER. Work Hygienic Practices: REMOVE AND LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. WASH THOROUGHLY AFTER USING. Supplemental Safety and Health THIS IS A KIT THAT CONTAINS 6 QUARTS RESIN AND 6 QUARTS HARDNER. CORROSIVE.

======= Physical/Chemical Properties ======

HCC:B3 Vapor Pres: