View NSN Online: https://aerobasegroup.gr/nsn/9525-00-529-0442

BROOKFIELD WIRE CO INC -- STAINLESS (300 & 400 SERIES), NI, NI-CU AND NI-CR-FE ALLOYS -- 9525-00-529-0442

============= Product Identification ========================

Product ID:STAINLESS (300 & 400 SERIES), NI, NI-CU AND NI-CR-FE ALLOYS

MSDS Date:10/13/1997

FSC:9525

NIIN:00-529-0442 Status Code:A

MSDS Number: CHYYQ === Responsible Party ===

Company Name: BROOKFIELD WIRE CO INC

Box:248

City:BROOKFIELD

State:MA

ZIP:01506-0248

Co

untry:US

Info Phone Num:617-867-6474

Emergency Phone Num:617-867-6474

CAGE:94129

=== Contractor Identification ===

Company Name: BROOKFIELD WIRE CO INC

Box:City:BROOKFIELD

State:MA

ZIP:01506-0248

Country:US

Phone:617-867-6474

CAGE:94129

======= Composition/Information on Ingredients ========

Ingred Name: CHROMIUM (SARA 313) (CERCLA)

CAS:7440-47-3

RTECS #:GB4200000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:1 MG/M3

ACGIH TLV:0.5 MG/M3; 9596

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred N

ame:COBALT (SARA 313)

CAS:7440-48-4

RTECS #:GF8750000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0.1 MG/M3

ACGIH TLV:0.02 MG/M3; A3; 9596

Ingred Name: COPPER (SARA 313) (CERCLA)

CAS:7440-50-8

RTECS #:GL5325000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0.1MG/M3 FUME/1 DUST

ACGIH TLV:0.2 MG/M3 FUME; 9596

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:IRON

CAS:7439-89-6

RTECS #:NO4565500

Other REC Limits: NONE RECOMMENDED

OSHA PEL:10 MG/M3 (TDUST)

ACGIH TLV:5 MG/M3 (OXIDE FUME)

Ingred Name

:MANGANESE (SARA 313)

CAS:7439-96-5

RTECS #: OO9275000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:C, 5 MG/M3 (FUME) ACGIH TLV:0.2 MG/M3; 9596

Ingred Name:MOLYBDENUM

CAS:7439-98-7

RTECS #:QA4680000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:10 PPM. ACGIH TLV:10 PPM.

Ingred Name: NICKEL (SARA 313) (CERCLA)

CAS:7440-02-0

RTECS #:QR5950000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:1 MG/M3


ACGIH TLV:1 MG/M3; 9596

Ingred Name: SILICON

CAS:7440-21-3

RTECS #: VW0400000

Other REC Limits: NONE RECOMMENDED



PROVIDE OXYGEN/CPR. FOR ELECTRIC SHOCK, DISCONNECT POWER, FOR ARC Н

WITH SOAP & WATER.

Flash Point:NONE

Lower Limits: NOT RELEVANT Upper Limits: NOT RELEVANT

Extinguishing Media: WATER SPRAY, CARBON DIOXIDE, FOAM OR DRY CHEMICAL FOR SURROUNDING FIRE. USE WATER SPRAY TO COOL FIRE EXPOSED CONTAINERS.

Fire Fighting Procedures: TREAT AS A METALLIC FIRE. WEAR PROTECTIVE CLOTHING AND NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS. Unusual Fire/Explosion Hazard: MAY FORM TOXIC FUMES.

SPARKS CAN IGNITE COMBUSTIBLES AND FLAMMABLES. ========= Accidental Release Measures ============== Spill Release Procedures: CLEAN UP ANY GRINDING DUST OR WASTE RESIDUE AND PLACE IN SUITABLE CONTAINER FOR DISPOSAL. AVOID GENERATING AIRBORNE DUST. AVOID INHALATION OF DUST. Neutralizing Agent: NOT RELEVANT ============= Handling and Storage ================= Handling and Storage Precautions: STORE IN A DRY PLACE AWAY FROM **INCOMPATIBL** ES. KEEP OUT OF REACH OF CHILDREN. Other Precautions: AVOID INHALATION AND EXCESSIVE SKIN CONTACT. AVOID BREATHING OF FUMES. USE WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING AND BEFORE EATING AND DRINKING. REMOVE CONTAMINATED CLOTHING, LAUND ER BEFORE REUSE. ====== Exposure Controls/Personal Protection ======== Respiratory Protection: USE NIOSH APPROVED SUPPLIED AIR RESPIRATORY PROTECTION OR RESPIRABLE FUME RESPIRATOR WHEN WELDING, BRAZING OR SOLDER ING IN CONFINED SPACE OR WHERE LOCAL EXHAUST VENTILATION DOES NOT KEEP EXPOSURE BELO W TLV. Ventilation: USE GENERAL & LOCAL EXHAUST AT FLAME TO KEEP FUMES AND GASES BELOW TLV'S IN THE WORKER'S BREATHING ZONE & GENERAL AREA. Protective Gloves:WELDER'S GLOVE Eye Protection: HELMET/FACE SHIELD WITH FILTER LENS Other Protective Equipment: EYE WASH STATION, SAFETY SHOWER, APRON (ALUMINIZED), EAR PROTECTION (TO AVOID EXCESSIVE NOISE) Work Hygienic Practices: OBSERVE GOOD PERSONAL HYGIENE PRAC TICES AND RECOMMENDED PROCEDURES. Supplemental Safety and Health ======== Physical/Chemical Properties =========== HCC:N1 NRC/State Lic Num: NOT RELEVANT Viscosity:NOT RELEVANT Evaporation Rate & Evaporation R Solubility in Water: INSOLUBLE Appearance and Odor:SOLID WIRE (ROUND OR FLATTENED) ======== Stability and Reactivity Data =========== Stability Indicator/Materials to Avoid:YES STRONG ACIDS Stability Condition to Avoid:WELDING ARCS

WELDING ARC AND

Haz

ardous Decomposition Products:WELDING FUMES	(OXIDES OF METAL BEING
WELD) AND GASES SUCH AS OZONE, CARBO	N MONOXIDE, CARBON DIOXIDE
NITROGEN OXIDES	

======= Disposal Considerations ===========

Waste Disposal Methods:DISPOSED OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS. PREVENT WASTE FROM CONTAMINATING ENVIRONMENT.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department

of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.