NSN 3510-01-505-1135

Repairability:

Loading Door Assembly Dryer - Page 1 of 1



When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.