

C-I-L CHEMICALS,INC. (SEE SUP DATA) -- SULPHUR DIOXIDE, BULK -- 6830-00-302-7974

=====
Product Identification
=====

Product ID:SULPHUR DIOXIDE, BULK

MSDS Date:01/01/1985

FSC:6830

NIIN:00-302-7974

MSDS Number: BDWPG

=== Responsible Party ===

Company Name:C-I-L CHEMICALS,INC. (SEE SUP DATA)

Emergency Phone Num:313-862-4747

CAGE:00049

=== Contractor Identification ===

Company Name:C-I-L CHEMICALS, IN

C. (SEE SUP DATA)

Phone:313-862-4747

CAGE:00049

=====
Composition/Information on Ingredients
=====

Ingred Name:SULFUR DIOXIDE (SARA III)

CAS:7446-09-5

RTECS #:WS4550000

Fraction by Wt: 100%

OSHA PEL:5 PPM/5 STEL

ACGIH TLV:2 PPM/5 STEL; 9293

=====
Hazards Identification
=====

Effects of Overexposure:SKIN:SEVERE BURNS.EYES:SEVERE

IRRIT/INFLAMM/POSS PERM DAMAGE.INH:SEVERE UPPER RESP TRACT,LUNG

IRRIT.

=====
First Ai

d Measures
=====

First Aid:SKIN:REMOVE CLTHNG IMMED/FLUSH W/H*20 MIN 15 MINS/GET MD/DO

NOT APPLY SALVES,OINTMENTS. EYES:WASH THOROUGHLY W/H*20 MIN 15

MINS/GET MD. INH:MOVE TO FRESH AIR/GIVE ART RESP,O*2 IF NEC/KEEP

WARM,QUIET/G ET MD. POSS RESP DISTRESS/PARALYSIS. SEE OTHER PRE

=====
Fire Fighting Measures
=====

Flash Point:NONE

Extinguishing Media:NONFLAMMABLE-USE AGENT SUITABLE FOR TYPE OF

SURROUNDING FIRE

Fire Fighting Pr

cedures:USE SCBA/PROT CLTHNG. USE H*2O TO COOL CNTNRS
UNLESS LEAKING

Unusual Fire/Explosion Hazard:CNTNRS WILL VENT @160F,71C/TANK CARS @225
PSIG IN FIRE OR WHEN HIGH PRESS APPLIED. SO*2 NOT EXPLOS.

===== Accidental Release Measures =====

Spill Release Procedures:MOVE UNPROTECT PERS.ISOLATE LEAK,POSITION
CNTNR SO IS GAS,NOT LIQ,LEAK.USE FULL PROTECT EQUIP,APPLY EMERGENCY
DEVICE IF POSS.NEVER IMMERSER LEAKING SO*2 CYLINDER IN H*2O.MAJOR
LEAKS:IMPL
EMENT EMERGENCY PLAN.HARMFUL TO AQUATIC LIFE,FORMS
ACIDIC MEDIA.

===== Handling and Storage =====

Handling and Storage Precautions:KEEP CNTNRS IN COOL,DRY,WELL-VENT AREA
W/NON-CONSTRUCT. SECURE TO PRVNT MOVEMENT/MECH DAMAGE. KEEP OUT OF
SUN/AWAY FROM DIRECT SOURCES OF HEAT.

Other Precautions:DO NOT SHIP LEAKING SO*2 CNTNRS. SEPERATE FROM
COMBUST MATL.IN CASE OF FIRE REMOVE SO*2 CNTNRS FROM FIRE ZONE IF
POSS. ING:TRANSPORT IMMED TO NEAREST
EMERGENCY MED FACILITY. GET MD
HELP PROMPT

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NIOSH/MSHA APPRVD FOR EXPOS OF CONCERN. SCBA FOR
HIGH/UNKNOWN CONC.

Ventilation:ADEQUATE TO KEEP GAS CONC BELOW TLV. VENT AT FLOOR LEVEL.

Protective Gloves:RUBBER/VINYL

Eye Protection:GASTIGHT CHEM GOG,SHIELD

Other Protective Equipment:SFTY SHOWER/EYE WASH.RUBBER
SHOES/SUIT,GASTIGHT BODY PROTECT

Supplemental Safety and Health

ADDRESS:800 MARION,RIVE

R ROUGE,MICH 48218. DIST:MANLEY REGAN CHEM, DIV

OF UNITED CHEM, INC. 717-944-7471. VAP PRESS:1323.7. VP & SP GRAV
MEASURED @60F,15.5C. STRONG SUFFOCATING, PUNGENT ODOR.

===== Physical/Chemical Properties =====

HCC:G1

Boiling Pt:B.P. Text:14F,-10C

Vapor Density:2.26

Spec Gravity:1.39

Solubility in Water:APPRECIABLE

Appearance and Odor:COLORLESS GAS OR LIQ BELOW 14F,-10C(SEE SUPP DATA)

===== Stability and Reactivity Data =====

Stabi

lity Indicator/Materials to Avoid: YES

STRONG ALKALIES, OXIDIZING AGENTS. MOIST GAS CORRODES METALS.

Stability Condition to Avoid: PRESENCE OF MOISTURE & HIGH TEMPS. STORAGE
IN CONFINED SPACE

Hazardous Decomposition Products: DOES NOT DECOMP; REACTS
W/H₂O/STEAM: PROD TOXIC, CORROSIV MATL

===== Disposal Considerations =====

Waste Disposal Methods: SO₂ CAN BE ABSORBED IN ALKALINE SOLN OF
NAOH, SODA ASH, HYDRATED LIME, NAHCO₃ WHICH MUST BE
OXIDIZED (E.G. H₂O

*2) BEFORE DISPOS DUE TO O₂ DEMAND. MAY BE DANGER
IF IT ENTERS H₂O INTAKES. DISPOSAL MUST B E IAW LOCAL, STATE &
FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document shou

ld seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.