View NSN Online: https://aerobasegroup.gr/nsn/5915-00-950-4194

Product ID:SP238 MSDS Date:01/01/1985 FSC:5915 NIIN:00-950-4194 MSDS Number: BFYWJ === Responsible Party === Company Name: FILTRON CO.INC. Address:148 SWEET HOLLOW RD City:OLD BETHPAGE State:NY ZIP:11804-1315 Country:US Emergency Phone Num:914-699-2000 CAGE:JO774 === Contractor Identification === Company Name: FILTRON CO INC Address:148 SWEET HOLLOW RD Box:City:OLD BETHPAGE State:NY ZIP:11804-1315 Country:US Phone:914-699-2000 CAGE:81831 Company Name: FILTRON CO.INC. Address:148 SWEET HOLLOW RD Box:City:OLD BETHPAGE State:NY ZIP:11804-1315 Country:US Phone:914-699-2000 CAGE: JO774

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III) CAS:1336-36-3 RTECS #:TQ1350000 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

======================= Hazards Identifica

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

First Aid:EYES:FLUSH W/WATER IMMED.SKIN:WASH W/SOAP IMMED.INHAL:REMOVE TO FRESH AIR.GIVE ART.RESPIR. AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNCONSCIOUS PE RSON VOMIT.
======================================
ase Measures ====================================
Spill Release Procedures:USE ABSORBENT & DIKES TO PREVENT RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.
======================================
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
======================================
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD Ventilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES FACE SHIELD
Other Protective Equipment: FULL CLOTHING TO PREVENT SKIN CONTACT Supplemental Safety and Health
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS.CAUSES STILLBIRTHS.IRRITATES EYES,NOSE,THROAT.
======================================
HCC:Z3 Appearance and Odor:LIGHT STRAW COLORED LIQUID,AROMATIC ODOR.
======================================
STRONG OXIDIZERS
======================================

Wast

e Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.