

GEORGIA PACIFIC CORPORATION -- METHANOL,METHYL ALCOHOL -- 6810-01-027-4771

=====  
===== Product Identification =====

Product ID:METHANOL,METHYL ALCOHOL

MSDS Date:01/01/1985

FSC:6810

NIIN:01-027-4771

MSDS Number: BGFRJ

=== Responsible Party ===

Company Name:GEORGIA PACIFIC CORPORATION

Address:7500 N WEST LN

Box:8040

City:STOCKTON

State:CA

ZIP:95210

Country:US

Emergency Phone Num:404-987-5190

CAGE:0802X

==

= Contractor Identification ===

Company Name:GEORGIA PACIFIC CORP

Address:2861 MILLER ROAD

Box:8040

City:DECATUR

State:GA

ZIP:30035

Country:US

Phone:404-987-5190

CAGE:0802X

Company Name:GEORGIA-PACIFIC CORP CHEMICAL PACKAGING DIV

Address:7500 N WEST LN

Box:8040

City:STOCKTON

State:CA

ZIP:95210

Country:US

Phone:209-477-5189

CAGE:1F887

=====  
===== Composition/Information on Ingredients =====

Ingred Name:METHYL ALCOHOL (METHANOL) (SARA III)

CAS:67-56-1

RTECS #:PC1400000

Fraction by W

t: 100%  
OSHA PEL:S,200PPM/250STEL  
ACGIH TLV:S,200PPM/250STEL; 93  
EPA Rpt Qty:5000 LBS  
DOT Rpt Qty:5000 LBS

=====  
Hazards Identification  
=====

Effects of Overexposure:INGESTED:MAY BE FATAL,BLINDNESS.INHALED OR REPEATED CONTACT:HARMFUL,EFFECTS MAY BE CUMULATIVE.

=====  
First Aid Measures  
=====

First Aid:SKIN:WASH W.SOAP & H\*2O EYES:FLUSH W. H\*2O. INGESTED:GIVE 2 GLASSES H\*2O; INDUCE VOMITING.CALL A PHYSICIAN. INHALE :REMOVE TO FRESH AIR. GIVE CPR/OXYGEN IF NEED. KEEP WARM & QUIET. REMOVE CONTAMINATED CLOTHING. IF UNCONS DO NOT TAKE ANYTHINGBY MOUTH.

=====  
Fire Fighting Measures  
=====

Flash Point:54F/12C TCC  
Lower Limits:7.3  
Upper Limits:36  
Extinguishing Media:SM:CO\*2, DRY CHEM. LG:H\*2O SPRAY,FOG OR FOAM  
Fire Fighting Procedures:WEAR CHEMICAL PROTECTIVE SUIT WITH SELF CONTD BRTHG APP.  
Unusual Fire/Explosion Hazard:EXTREMELY FLAMMABLE CONTAINER MAY EXPLODE.  
VAPOR IS EXPLOS HAZARD.VAPOR MAY SPREAD AWAY FROM SPILL.

=====  
Accidental Release Measures  
=====

Spill Release Procedures:REMOVE IGNITION SOURCES,VENTILATE AREA WELL.ABSORB WITH VERMICULITE OR OTHER MATERIALS, SUCH AS SAWDUST,RAGS,PAPER & PLACE IN CLOSED CONTAINER. USE NON SPARKING TOOLS. WEAR PROPER PROTECTIVE EQUIPMENT DURING CLEAN UP-FLUSH AREA WITH WATER.

=====  
Handling and Storage  
=====

Handling and Storage

Precautions:STORAGE TANKS & MATERIAL HANDLING  
LINES SHOULD BE GROUMDED.STORE IN DRY,LOW FIRE RISK AREA.AVOID  
ALKALI.

Other Precautions:NO SMOKING.AIR PRESSURE SHOULD NEVER BE USED FOR  
UNLOADING TANK TRUCKS OF METHANOL.

=====  
===== Exposure Controls/Personal Protection =====

Respiratory Protection:(1)SCBA(2)APPRVD INDUS. CANISTER TYPE GAS MASKS.  
Ventilation:MECH(GEN)OR LOCAL EXHAUST THAT PROVIDES ADEQUATE  
VENTILATION

Protective Gloves:RUBBER

Eye Protection:CUP/RUBBER  
FRAMED GOGGLES

Other Protective Equipment:FACE SHIELDING

Supplemental Safety and Health

=====  
===== Physical/Chemical Properties =====

HCC:F2

Boiling Pt:B.P. Text:148F/64C

Vapor Pres:96

Vapor Density:0.79

Spec Gravity:0.1924

Evaporation Rate & Reference:NO INFO PER MFR.

Solubility in Water:COMPLETE

Appearance and Odor:MILD ODOR-NON-IRRITATING.

Percent Volatiles by Volume:100

=====  
===== Stability and Reactivity Data =====

Stability Indicator/Mat

erials to Avoid:YES

CAUSTIC(ALKALI)

Stability Condition to Avoid:HEAT,STATIC ELECTRICITY

Hazardous Decomposition Products:NONE NOTED,BUT EXPECT CO, CO\*2, H\*2O.

=====  
===== Disposal Considerations =====

Waste Disposal Methods:ELIMINATE IGNITION SOURCES. DESTROY BY LIQUID  
INCINERATION. INCINERATION WILL BE EASIER BY MIXING WITH A MORE  
FLAMMABLE SOLVENT. HANDLE & DISPOSE IN FULL COMPLIANCE WITH ALL  
APPLICABLE INTERNATIONAL,F ED,STATE & LOCAL REGULATIONS.

sclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.