NATIONAL WELDERS -- NITROGEN -- 6830-01-122-2652

Product ID:NITROGEN MSDS Date:11/20/1988 FSC:6830 NIIN:01-122-2652 MSDS Number: BHFDZ === Responsible Party === Company Name:NATIONAL WELDERS Address:810 GESCO Box:31007 City:CHARLOTTE State:NC ZIP:28231 Country:US CAGE:18264 === Contractor Identification === Company Name: NATIONAL WELDERS SUPPLY CO INC Address:810 GESCO ST Box:31007 City:CHARLOTTE State:NC ZIP:28231 Country:US Phone:704-333-5475 CAGE:18264

Ingred Name:NITROGEN CAS:7727-37-9 RTECS #:QW9700000 ACGIH TLV:ASPHYXIANT; 9192

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:NITROGEN IS A SIMPLE ASPHYXIANT. NITROG

- EN IS NONTOXIC BUT IN THE LIBERATION OF ALARGE AMOUNT IN A CONFINED AREA COULD DISPLACE THE AMOUNT OF OXYGEN IN AIR NECESSARY TO SUPPORT LIFE.
- Effects of Overexposure:SYMPTOMS INCLUDE: DIZZINES, TIGHTNESS OF FOREHEAD, TINGLING OF TONGUE, FINGERTIP& TOES, WEAKENED SPEECH, RAPID REDUCTION IN ABILITY TO PERFORM MOVEMENTS, RE- DUCED CONSCIOUSNESS OF SURROUNDINGS, LOS S OF TACTILE SENSATIONS, HEIGHTENEDMENTAL ACTIVITY. ANY, ALL, OR NONE OF THE ABOVE MAY OCCUR.

First Aid:INHALATION: CONSCIOUS PERSONS SHOULD BE ASSISTED TO AN UNCONTAMINATED AREA AND INHALE FRESH AIR. UNCONSCIOUS PERSON SHOULD BE MOVED TO UNCONTAMINATED AREA AND GIVEN CPR AND SUPPLEMENTAL OXYGEN. FURTH ER TREATMENT SHOULD BE SYMPTOMATIC ANDSUPPORTIVE.

Extinguishing Media:NONFLAMMABLE, INERT GAS

================== Accidental Release Measure

Spill Release Procedures: EVACUATE ALL PERONNEL FROM AREA. USE APPROPRIATE PROTECTIVE EQUIP. IF LEAK IS IN CONTAINER OR CON-TAINER VALVE, CONTACT YOUR CLOSEST SUPPLIER.

Handling and Storage Precautions:USE/STORE IN COOL, DRY, WELL
VENTILATED AREA.STORECYLINDERS UPRIGHT & FIRMLY SECURED.DO NOT LET
TEMPEXCEED 130F. SEGREGATE FULL/EMPTY CYLINDERS.
Other Precautions:COMPRESSED GAS CYLINDERS
SHOULD NOT BE REFILLED
EXCEPT BY QUALIFIED PRODUCERS OFCOMPRESSED GASES. USE A CHECK VALVE
OR TRAP IN THE DISCHARGE LINE TO PREVENT HAZARDOUS BACK FLOW
INTO THE CYL. VALVE PROTECTION CAPS MUST REMAIN IN PLACE.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection: POSITIVE PRESSURE AIR LINE WITH MASK OR SELF-CONTAINED BREATHING APPARATUS SHOULD BE AVAILABLE FOR EMERGENCY USE. Ventilation: TO PREVENT ACCUMULATION OF HIGH CONCENTRATION S SO AS TO REDUCE THE OXYGEN LEVEL IN THE AIR TO LESS THAN 18 MOLAR %. Protective Gloves: ANY MATERIAL Eye Protection: SAFETY GOGGLES OR GLASSES Other Protective Equipment: SAFETY SHOES Supplemental Safety and Health NK

Boiling Pt:B.P. Text:-320F/-195C Vapor Pres:*SEE BELOW Vapor Density:*SEE BELOW Spec Gravity: @70F/21C = 0.97 Solubility in Water: VERY SLIGHTLY Appearance and Odor:COLORLESS, ODORLESS GAS

Stability Indicator/Materials to Avoid:YES NK *VAP DENS: .0725 LB/FT3 (1.161 KG/M3) Stability Condition to Avoid:NK *VAP PRES:@70F/21C ABOVE THE CRITICAL TEMP OF -232F/-147C

Waste Disposal Methods: DO NOT ATTEMPT TO DISPOSE OF WASTE OR UNUSED QUANTITIES.RETURN IN THE SHIPPING CONTAINER PROPERLY LABELED, WITH ANY VALVE OUTLET PLUGS OR CAPS SECURED & VALVE PR OTECTION CAP IN PLACE TO YOUR SUPPLIER.FOR EMERG DISPOSAL CONTACT YOUR SUPPLIER.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and

а

ssume responsibility for the suitability of this information to their particular situation.