DOW CORNING CORP. -- G-N METAL ASSEMBLY PASTE -- 9150-01-037-9016

Product ID:G-N METAL ASSEMBLY PASTE MSDS Date:04/25/1990 FSC:9150 NIIN:01-037-9016 MSDS Number: BMTQQ === Responsible Party === Company Name: DOW CORNING CORP. Address:3901 S SAGINAW ROAD Box:997 City:MIDLAND State:MI ZIP:48640 Country:US Info Phone Num:517-496-5900 Emergency Phone Num:517-496-5900 Preparer's Name: JACK L.SHENEBERGER CAGE:5D028 === Contractor Identification === Company Name: DOW CORNING CORP Address:3901 S SAGINAW RD Box:997 City:MIDLAND State:MI ZIP:48686-0997 Country:US Phone:517-496-6000/517-496-6315 CAGE:5D028 Company Name: DOW CORNING CORP Address:2200 W SALZBURG RD Box:City:AUBURN State:MI ZIP:48611 Country:US Phone:517-496-4388 CAGE:71984 Company Name: INLAND PACKAGING Box:644 City:ELIZABETHTOWN State:KY ZIP:42701 Country:US Phone:502-737-6758 CAGE:6U655

Composition/Information on Ingredients =========

Ingred Name:MINERAL OIL (EXPOSURE REGULATED AS 'OIL MIST') CAS:8012-95-1 RTECS #:PY8030000 Fraction by Wt: 48% Other REC Limits:5 MG/M3 OIL MIST OSHA PEL:5 MG/M3 ACGIH TLV:5 MG/M3/10 STEL;9192

Ingred Name:MOLYBDENUM DISULFIDE CAS:1317-33-5 RTECS #:QA4697000 Fraction by Wt: 17% Other REC Limits:NONE SPECIFIED BY M. OSHA PEL:10 MG/M3 TDUST (MO) ACGIH TLV:10 MG/M3 (MO); 8990

Ingred Name:SILICA GEL CAS:112945-52-5 RTECS #:VV7310000 Fraction b y Wt: 1.0% Other REC Limits:NONE SPECIFIED OSHA PEL:6 MG/M3 ACGIH TLV:10 MG/M3 TOTAL DUST

Ingred Name:ZINC PROPHOSPHATE CAS:7446-26-6 Fraction by Wt: 14% Other REC Limits:NONE SPECIFIED

Ingred Name:CALCIUM PHOSPHATE CAS:10103-46-5 Fraction by Wt: 13% Other REC Limits:NONE SPECIFIED

Ingred Name:ETHYLENE-BIS-STEARAMIDE CAS:110-30-5 Fraction by Wt: 3% Other REC Limits:NONE SPECIFIED

Ingred Name:TRIALUMINUM PHOSPHATE CAS:13530-50-2 Fraction by Wt: 2.0% Other REC Limits:NONE SPECIFIED

==========

Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:SKIN:PROLONGED EXPOSURE MAY CAUSE IRRITATION.EYES:DIRECT CONTACT MAY CAUSE IRRITATION.INHAL:MAY CAUSE SLIGHT RESPIRATORY IRRITATION.INGEST:INTENTIONAL INGESTION OF LARGE QUANTITIES MAY CAUSE DIGESTIVE TRACT DISCOMFORT. Explanation of Carcinogenicity:THERE ARE NO INGREDIENTS ABOVE 0.1%

WHICH ARE IDENTIFIED AS CARCINOGENS BY NTP, IARC OR OSHA. Effects of Overexposure:EYES:REDNESS AND SWELLING. Medical Cond Aggravated by Exposure:PERSONS WITH ALLERGIC CONDITIONS MAY BE AT INCREASED RISK FROM EXPOSURE.

First Aid:EYES:FLUSH WITH WATER.SKIN:WIPE OFF;FLUSH WITH SOAP AND WATER(WATERLESS CLEANER MAY BE USED).INHAL:NO FIRST AID SHOULD BE NEEDED.INGEST:NO FIRST AID SHOULD BE NEEDED.

Flash Point Method:OC Flash Point:>250F/121C Extinguishing Media:WATER FOG, DRY CHEMICAL, CARBON DIOXIDE, FOAM. Fire Fighting Procedures:SELF-CONTAINED BREATHING APPARATUS & PROTECTIVE CLOTHING. Unusual Fire/Explosion Hazard:HAZARDOUS SULFUR OXIDES FORM.

Spill Release Procedures:REMOVE PRODUCT.CLEAN SPILL AREA TO REMOVE SLIPPERINESS. Neutralizing Agent:NONE

Handling and Storage Precautions: USE REASONABLE CARE IN HANDLING THIS PRODUCT.

Other Precautions:NONE

Respiratory Protection:NONE SHOULD BE NEEDED IN NORMAL SERVICE. Ventilation:MECHANICAL(GENERAL) RECOMMENDED. Protective Gloves:AS NEEDED Eye Protection:SAFETY GLASSES(AS MINIMUM) Other Protective Equipment:EYE WASH STATION. Work Hygienic Practices:WASH HANDS BEFORE EATING AND AT END OF SHIFT. Supplemental Safety and Health NONE

HCC:V7 Vapor Pres: