View NSN Online: https://aerobasegroup.gr/nsn/6550-01-234-5062

BECTON DICKINSON MICROBIOLOGY SYSTEMS -- BBL PREPARED MEDIA (PLATES) 6550-01-234-5062

Product ID:BBL PREPARED MEDIA (PLATES) MSDS Date:10/31/1990 FSC:6550 NIIN:01-234-5062 MSDS Number: BNQDT === Responsible Party === Company Name: BECTON DICKINSON MICROBIOLOGY SYSTEMS Address:250 SCHILLING CIRCLE Box:243 City:COCKEYSVILLE State:MD ZIP:21030 Country:US Info Phon e Num:301-584-7169 Emergency Phone Num:301-666-0100 CAGE:06531 === Contractor Identification === Company Name: BECTON DICKINSON AND CO MICROBIOLOGY SYSTEMS DIV Address:250 SCHILLING CIRCLE Box:City:HUNT VALLEY State:MD ZIP:21030-1103 Country:US Phone:410-771-0101 CAGE:05545 Company Name: BECTON DICKINSON AND CO, BECTON DICKINSON DIV. Address:1 BECTON DR **City:FRANKLIN LAKES** State:NJ ZIP:07417-1884 Country:US Phone:201-847-4000, 800-333-4831 CAGE:06531 Company Name: CURTIN MATHESON SCIENTIFIC, INC. А

ddress:22745 SAVI RANCH PKWY Box:City:YORBA LINDA State:CA ZIP:92687-7904 Country:US Phone:714-637-2200 CAGE:6X755 Ingred Name: PREPARED PLATED MEDIA LD50 LC50 Mixture: NONE SPECIFIED BY MANUFACTURER. Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: THIS PRODUCT CONTAIN S NO HAZARDOUS MATERIALS AS DEFINED BY THE OSHA HAZARD COMMUNICATIONS STANDARD. HOWEVER, INDIVIDUALS WITH KNOWN OR SUSPECTED ALLEERTIES SHOULD ADVISE PHYSICIAN OF INCIDENT THAT MAY HAVE RESULTED IN EXPOSURE TO ANTIBIOTIC TREATED MEDIA. Explanation of Carcinogenicity:MFR SAID "NOT APPLICIABLE" IN THIS FIELD. Effects of Overexposure: MFR SAID "NOT APPLICIABLE" IN THIS FIELD. Medical Cond Aggravated by Exposure:MFR SAID "NOT APPLICIABLE" IN THIS FIELD. _____ First Aid:MFR SAID "NOT APPLICIABLE" IN THIS FIELD. Flash Point:N/D Lower Limits:N/D Upper Limits:N/D Extinguishing Media:WATER SPRAY. Fire Fighting Procedures: MFR SAID "NOT APPLICIABLE" IN THIS FIELD. Unusual Fire/Explosion Hazard: PRODUCT WILL NOT BURN. IF PROD BECOMES INVOLVED IN A FIRE SITUATION EXTING MEDIA FOR SURROUNDING MATERIAL SHOULD BE APPROPRIATE.

=========

	Accidental	Release	Measures	
--	------------	---------	----------	--

Spill Release Procedures:USE PAPER TOWELS TO PICK UP GELLED MATERIAL.
WASH AREA WITH SOAP AND WATER AFTER CLEANUP IS COMPLETE. SEE WASTE DISPOSAL FOR PROPER DISPOSAL.
Neutralizing Agent:SUPPLIER DID NOT ADDRESS THIS FIELD.

Handling and Storage Precautions: GOOD PERSONAL HYGIENE SHOULD BE PRACTICED.

Other Precautions:(FM WASTE DISP.) DIRECTIONS FOR USE SHOUL D BE READ

AND FOLLOWEED CAREFULLY. FOLLOW ALL CURRENT FEDERAL, STATE AND LOCAL REGULATIONS.

Respiratory Protection:NOT REQUIRED UNDER NORMAL PRODUCT USAGE. Protective Gloves:LATEX GLOVES RECOMMENDED; NOT REQUIRED Eye Protection:SAFETY GLASSES Other Protective Equipment:NOT REQUIRED UNDER NORMAL PRODUCT USAGE. Work Hygienic Practices:SUPPLIER DID NOT ADDRESS THIS FIELD. Supplemental Safety and Health 1*MSDS RECEIVED FRO M NAVY (FOCAL POINT N). NAVY IDENTIFIED NSN.

HCC:N1

Appearance and Odor:GELLED MEDIUM OF VARING COLORS.

Stability Indicator/Materials to Avoid:YES

N/D

Stability Condition to Avoid:N/D (NOT DETERMINED)

Hazardous Decomposition Products:N/D

Conditions to Avoid Polymerization:WILL NOT OCCUR.

Waste Disposal Methods:OBSERVE ANTISEPTIC TECHNIQUES AND ESTABLISHED PRECAUTIONS AGAINST MICROBIOLOGICAL HAZARDS THROUGHOUT ALL PROCEDURES. AFTER USE, PREPARED PLATES, SPECIMEN CONTAINERS AND OTHER CONTAMINATED MATERIALS MU ST BE STERILIZED BY AUTOCLAVING. (CONT OTHER PREC)

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever

expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.