Product ID:064-22745A MSDS Date:09/30/1992

FSC:5330

NIIN:00-469-8211

MSDS Number: BNVYP === Responsible Party ===

Company Name: YORK INTERNATIONAL CORP

Address:631 S RICHLAND AVE

Box:1592 City:YORK State:PA ZIP:17403 Country:US

Info Phone Num:717-771-7890

Emergency Phone Num:717-771-7890

Preparer's Name:DGS

C-SSH

CAGE:66935

=== Contractor Identification ===

Company Name: CHESAPEAKE ASSOC. ENT.

Address:22 NEWPORT DR Box:City:FOREST HILL

State:MD ZIP:21050 Country:US

Phone:410-838-0260

CAGE:7R834

Company Name: YORK INTERNATIONAL CORP

Address:631 S RICHLAND AVE

Box:City:YORK

State:PA ZIP:17403 Country:US

Phone:717-771-7890

CAGE:66935

====== Composition/Information on Ingredients ========

Ingred Name: ASBESTOS, CHRYSOTILE

CAS:12001-29-5 RTECS #:Cl6478500

Other REC Limits: NONE RECOMMENDED


0

SHA PEL:0.2 FIBERS/CC ACGIH TLV:2 FIBERS/CC; A1;9192
============ Hazards Identification =============
Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES Health Hazards Acute and Chronic:PROLONGED OR REPEATED EXPOSURE TO AIRBORNE ASBESTOS FIBERS FROM SANDING, CUTTING, SCRAPPING, FILING, ETC. MAY LEAD TO ASBESTOSIS AND MESOTHELIOMA. SMOKING COMBINED WITH FIBER INHALATION GREATLY INCREA SES LUNG CANCER R ISK.
Explanation of Carcinogenicity:OVEREXPOSURE TO AIRBORNE CONCENTRATIONS OF ASBESTOS MAY LEAD TO ASBESTOSIS AND MESOTHELIOMA. Effects of Overexposure:INHALATION OF AIRBORNE DUST CONTAINING ASBESTOS FIBERS ON REPEATED EXPOSURE MAY CAUSE OR CAN LEAD TO ASBESTOSIS / MESOTHELIOMA; DUST MAY CAUSE EYE IRRITATION. Medical Cond Aggravated by Exposure:PERSONS WITH RESPIRATORY DISEASE OR PERSONS WHO SMOKE MAY BE AT INCREASED RISK FROM EXPOSURE TO DUST CONTAINING ASBESTOS FIBERS.
== ===================================
First Aid:INHALATION: REMOVE TO FRESH AIR. GET MEDICAL ATTENTION. EYE: PROMPTLY FLUSH WITH RUNNING WATER FOR 15 MINUTES WHILE LIFTING EYELID. GET MEDICAL ATTENTION. SKIN: PROMPTLY FLUSH WITH SOAP AND WATER. REM OVE CONTAMINATED CLOTHING. GET MEDICAL ATTENTION IF IRRITATION PERSISTS. INGESTION: GET MEDICAL ATTENTION AS REQUIRED.
======================================
Flash Point:NON
Autoignition Temp:Autoignition Temp Text:NONE Extinguishing Media:MATERIAL IS NOT FLAMMABLE; USE MEDIA APPROPRIATE FOR SURROUNDING FIRE.
Fire Fighting Procedures: COMBUSTION PRODUCTS OF THIS MATERIAL MAY BE TOXIC. USE A SELF-CONTAINED BREATHING APPARATUS WHEN FIGHTING FIRES

Unusual Fire/Explosion Hazard:NONE

========= Accidental Release Measures ===============

Spill Release Procedures: USE PROPER PERSONAL PROTECTION. VACUUM OR WET CL



Waste Disposal Methods:DUST SHOULD BE HANDLED AS A HAZARDOUS AIR POLLUTANT I/A/W 40CFR61 SUBPART "M" PERTAINING TO ASBESTOS. USE LANDFILLS APPROVED FOR ASBESTOS DISPOSAL. INDICATE IF ITEM UNDER CONSIDERATION FOR DISPOSAL IS "FRIABLE OR NON-FRIABLE".

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or impli

ed, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.