

WEISS INSTRUMENTS INC -- THERMOMETER-INDUSTRIAL 5,7,9 OR 12" CASE -- 6685-00-242-2158

=====
Product Identification
=====

Product ID:THERMOMETER-INDUSTRIAL 5,7,9 OR 12" CASE
MSDS Date:10/26/1990
FSC:6685
NIIN:00-242-2158
MSDS Number: BTHLX
=== Responsible Party ===
Company Name:WEISS INSTRUMENTS INC
Address:85 BELL ST
City:WEST BABYLON
State:NY
ZIP:11704-1086
Country:US
Info Phone Num:516-752-1655
Emergency Phone Num:516-752-1655,800-424-9300(CHEMTREC)
Preparer's Name:NONE
CAGE:14449
=== Contractor Identification ===
Company Name:WEISS INSTRUMENTS INC
Address:905 WAVERLY AVE
Box:City:HOLTSVILLE
State:NY
ZIP:11742
Country:US
Phone:631-207-1200/ FAX: 631-207-0900
CAGE:14449

=====
Composition/Information on Ingredients
=====

Ingred Name:MERCURY (SARA III)
CAS:7439-97-6
RTECS #:OV4550000
Fraction by Wt: 100%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:S, C, 0.1 MG/M3
ACGIH

TLV:S, 0.05 MG/M3; 9394

EPA Rpt Qty:1 LB

DOT Rpt Qty:1 LB

===== Hazards Identification =====

LD50 LC50 Mixture:ORAL LD50 (RAT) IS UNKNOWN.

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:THERMOMETER CONTAINS SMALL AMOUNT OF MERCURY ENCLOSED IN A GLASS TUBE. HAZARDOUS ONLY IF BROKEN. FOR MERCURY ITSELF: ACUTE: INHALATION OF HIGH CONCENTRATIONS OF MERCURY

V
APOR CAN CAUSE KIDNEY, LIVER,C NS DAMAGE. CHRONIC: EXPOSURE TO MERCURYOVER LONG PERIOD OF TIME MAY CAUSE TREMORS,IRRITABILITY,KIDNEY,LIVER,CNS DAMAGE.

Explanation of Carcinogenicity:NONE

Effects of Overexposure:FOR MERCURY ITSELF: ACUTE POISONING THROUGH MASSIVE INHALATION OF MERCURY FUMES IS RARE. SYMPTOMS ARE, COUGH, FEVER, METALLIC TASTE. CHRONIC EXPOSURE OVER A LONG PERIOD OF TIME MAY CAUSE TREMORS, IRRI TABILITY, KIDNEY, LIVER, AND CENTRAL NERVOUS SYSTEM DAMAGE.

Medi
cal Cond Aggravated by Exposure:PERSONS WITH CHRONIC DISEASE OR IN POOR HEALTH, SHOULD BE EXCLUDED FROM MERCURY WORK AREA.

===== First Aid Measures =====

First Aid:FOR MERCURY ITSFLF: GET MEDICAL ATTENTION IF EXPOSED TO MERCURY FUMES OR INGESTED MERCURY LIQUID.

===== Fire Fighting Measures =====

Flash Point:NON-FLAMMABLE

Extinguishing Media:NOT COMBUSTIBLE. USE MEDIA SUITABLE FOR SURROUNDING FIRE.

Fire Fightin

g Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS WITH WATER SPRAY. CONTAIN RUNOFF.

Unusual Fire/Explosion Hazard:MERCURY IS NOT COMBUSTIBLE, BUT WILL VAPORIZE RAPIDLY WHEN HEATED, CREATING TOXIC FUMES.

===== Accidental Release Measures =====

Spill Release Procedures:TAKE UP WITH ABSORBENT MATERIALS AND PLACE IN CONTAINER FOR LATER DISPOSAL OR RECLAMATION.

Neutralizi

ng Agent:NONE SPECIFIED BY MANUFACTURER.

=====
===== Handling and Storage =====

Handling and Storage Precautions:HANDLE AND STORE THERMOMETER WITH CARE.

Other Precautions:INSPECT THERMOMETER FOR DAMAGE BEFORE HANDLING OR STORAGE.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NONE NORMALLY REQUIRED FOR MERCURY THERMOMETER. IF RESPIRATORY PROTECTION NEEDED FOR MERCURY USE A NIOSH/MSHA CERTIFIED RESPIRATOR OR MASK.

Ventilation:NONE NORMALLY REQUIRED FOR MERCURY THERMOMETER.

Protective Gloves:NONE REQUIRED FOR MERCURY THERMOMETER.

Eye Protection:NONE REQUIRED FOR MERCURY THERMOMETER.

Other Protective Equipment:NONE NORMALLY REQUIRED FOR THERMOMETER.

Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES.

Supplemental Safety and Health

MERCURY IS A PROBLEM ONLY IF THERMOMETER IS BROKEN AND MERCURY RELEASED. THERMOMETER CONTAINS APPROXIMATELY 0.45 CC OF MERCURY.

=====
===== Physical/Chemical Properties =====

HCC:Z2

Boiling Pt:B.P. Text:676F,358C

Melt/Freeze Pt:M.P/F.P Text:-38F,-39C

Vapor Pres:0.0019

Vapor Density:7.0

Spec Gravity:13.54

Solubility in Water:INSOLUBLE

Appearance and Odor:SILVER WHITE LIQUID METAL IN GLASS. ODORLESS.

=====
===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

MERCURY FORMS AMALGAMS WITH SILVER AND GOLD.

Stability Condition to Avoid:EXTREMEL

Y HIGH TEMPERATURES BEYOND
MEASURING RANGE OF THERMOMETER

Hazardous Decomposition Products:MERCURY FUMES AND MERCURY COMPOUNDS
ARE INDUSTRIAL POISONS.

Conditions to Avoid Polymerization:WILL NOT OCCUR.

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF WASTE IN ACCORDANCE WITH LOCAL, STATE
AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by ele
ments of the Department

of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.