

HENRY W W CO -- CERAMIC TILE ADHESIVE -- 8040-00-936-9944

=====  
Product Identification  
=====

Product ID:CERAMIC TILE ADHESIVE

MSDS Date:01/01/1994

FSC:8040

NIIN:00-936-9944

MSDS Number: BYXVP

=== Responsible Party ===

Company Name:HENRY W W CO

Address:5608 SOTO ST

City:HUNTINGTON PARK

State:CA

ZIP:90255-2629

Country:US

Info Phone Num:213-583-4961 / FAX 213-582-8451

Emergency Phone Num:800-424-930

0 (CHEMTREC)

Preparer's Name:C. A. EISENHARD

CAGE:11761

=== Contractor Identification ===

Company Name:CHEMICAL COMMODITIES AGENCY, INC.

Address:27447 PACIFIC STREET

Box:City:HIGHLAND

State:CA

ZIP:92346-2640

Country:US

Phone:909-864-2310

CAGE:60777

Company Name:HENRY W W CO

Address:Box:3001

City:LANCASTER

State:PA

ZIP:17604

Country:US

Phone:717-396-2328;717-396-2935

CAGE:11761

=====  
Composition/Information on Ingredients  
=====

Ingred Name:PETROLEUM DISTILLATE (VP = 5 MM @ 72F

)  
CAS:124-18-5  
RTECS #:HD6550000  
Fraction by Wt: 6-8%  
Other REC Limits:NONE RECOMMENDED  
OSHA PEL:500 PPM  
ACGIH TLV:500 PPM

Ingred Name:ETHYLENE GLYCOL (SARA 313) (CERCLA) (VP = 0.05 MM @ 68F)  
CAS:107-21-1  
RTECS #:KW2975000  
Fraction by Wt: 1-2%  
Other REC Limits:NONE RECOMMENDED  
OSHA PEL:100 PPM  
ACGIH TLV:100 PPM  
EPA Rpt Qty:1 LB  
DOT Rpt Qty:1 LB

===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO  
Reports of Carcinogenicity  
:NTP:NO IARC:NO OSHA:NO  
Effects of Overexposure:EXTREME OVEREXPOSURE: HEADACHE, NAUSEA,  
DIZZINESS.

===== First Aid Measures =====

First Aid:INHALATION: GET FRESH AIR. EYES: FLUSH W/WATER. INGESTION:  
CALL DR. SKIN: WASH W/SOAP & WATER.

===== Fire Fighting Measures =====

Flash Point:>200F,>93C  
Extinguishing Media:NOT FLAMMABLE. USE APPROPRIATE MEDIA FOR  
SURROUNDING FIRE.  
Fire Fighting Procedures:SCBA & FULL  
PROTECTIVE CLOTHING & GEAR.  
Unusual Fire/Explosion Hazard:NONE

===== Accidental Release Measures =====

Spill Release Procedures:SCOOP INTO CONTAINERS & ALLOW TO DRY.

===== Handling and Storage =====

Handling and Storage Precautions:AVOID HEATING ABOVE 220F.  
Other Precautions:KEEP AWAY FROM CHILDREN.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NOT REQUIRED.  
Ventilation:NORMAL VENTIL

ATION TO PROMOTE DRYING.

Protective Gloves:ONLY TO AVOID STICKY HANDS.

Eye Protection:NOT NOTMALLY REQUIRED.

Other Protective Equipment:IMPERVIOUS CLOTHING, EYEWASH FOUNTAIN, QUICK DRENCH SHOWER.

Supplemental Safety and Health

NK

===== Physical/Chemical Properties =====

Boiling Pt:B.P. Text:210 TO 285F

Melt/Freeze Pt:M.P/F.P Text:NA

Vapor Pres:NA

Vapor Density:NA

Spec Gravity: 9.6 LBS

Evaporation Rate & Reference:SLOWER THAN ETHER

Solubility in Water:NA

Appe

arance and Odor:EMULSION LATEX ADHEASIVE, CREAM COLOR

Percent Volatiles by Volume:40-50

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

STRONG OXIDIZING AGENTS.

Stability Condition to Avoid:TEMPERATURES OVER 140F.

Hazardous Decomposition Products:IN FIRE, SMOKE & OXIDES OF CARBON.

===== Disposal Considerations =====

Waste Disposal Methods:NORMAL SOLID DISPOSAL PER GOVERNMENT REGULATIONS.

=====  
=====

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility f

or the suitability of this information to their particular situation.