

AQUA BORNE COATING SYSTEMS INC -- 10501 UNIVERSAL COMPONENT,PART-A --
8010-01-375-5637

=====
===== Product Identification =====

Product ID:10501 UNIVERSAL COMPONENT,PART-A
MSDS Date:09/27/1995
FSC:8010
NIIN:01-375-5637
MSDS Number: BZGCX
=== Responsible Party ===
Company Name:AQUA BORNE COATING SYSTEMS INC
Address:805 DIXON RD
City:JONESBORO
State:GA
ZIP:30236-3177
Country:US
Info Phone Num:800-868-7711
/404-477-6688
Emergency Phone Num:800-535-5053/404-477-6688
CAGE:0J879

==== Contractor Identification ===
Company Name:AQUA BORNE COATING SYSTEM INC
Box:City:ATLANTA
State:GA
ZIP:30236
Country:US
Phone:404-477-6688
CAGE:0J879

=====
===== Composition/Information on Ingredients =====

Ingred Name:ETHYLENE GLYCOL PROPYL ETHER, EKTASOLVE EP,
2-PROPOXYETHANOL
CAS:2807-30-9
RTECS #:KM2800000
Fraction by Wt: 9%
OSHA PEL:25 PPM
ACGIH TLV:25 PPM

Ingred Name:EPOXY RESIN
Fraction by Wt: 51

=====
Hazards Identification
=====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:EYES: SEVERELY IRRITATING. SKIN:
MODERATELY IRRITATING, DERMATITIS/SENSITIZATION, HARMFUL IF
ABSORBED. INHALATION: HARMFUL, IRRITATION TO NOSE/THROAT &
RESPIRATORY TRACT, SENSITIZER. INGESTION: MODERATELY
TOXIC/HARMFUL. OVEREXPOSURE TO SOLVENTS MAY CAUSE ADVERSE EFFECTS
TO THE LIVER/URINARY/BLOOD FORMING SYSTEM.
Explanation of Carcinogenicity:NONE
Effects of Overexposure:IRRITATION.
Medical Conditions Aggravated by Exposure:PRE-EXISTING EYE, SKIN, RESPIRATORY
& BLOOD FORMING DISORDERS.

=====
First Aid Measures
=====

First Aid:INHALATION: REMOVE TO FRESH AIR. GIVE OXYGEN IF NEEDED. SKIN:
WASH AREA W/SOAP & WATER. EYES: FLUSH W/LARGE AMOUNTS OF WATER FOR
15 MINS. INGESTION: DON'T INDUCE VOMITING. IF VOMITING OCCURS
SPONTANEOUSLY, KEEP HEAD BELOW HIPS TO PREVENT ASPIRATION. IF >2
ML/KG OF BODY WEIGHT OCCURRED, INDUCE EMESIS W/SUPERVISION. GASTRIC
LAVAGE W/CUFFED ENDOTRACHEAL TUBE. OBTAIN MEDICAL ATTENTION IN ALL
CASES.

=====
Fire Fighting Measures
=====

Flash Point Method:SCC
Flash Point:>201F
Extinguishing Media:CO2, DRY CHEMICAL/FOAM
Fire Fighting Procedures:WEAR FULL PROTECTIVE EQUIPMENT & POSITIVE
PRESSURE NIOSH APPROVED SCBA. WATER SPRAY MAY
BE INEFFECTIVE IN
CONTROLLING FIRE, BUT MAY BE USED TO COOL CONTAINERS.
Unusual Fire/Explosion Hazard:CLOSED CONTAINERS EXPOSED TO EXTREME HEAT
MAY EXPLODE. NEVER USE A WELDING/CUTTING TORCH ON/NEAR EMPTY
CONTAINERS, RESIDUE MAY IGNITE.

=====
Accidental Release Measures
=====

Spill Release Procedures:REMOVE SOURCES OF IGNITION. PREVENT BREATHING
OF VAPORS. VENTILATE AREA. CONTAIN & REMOVE W/INERT ABSORBENT USING
NON-SPARKING TOOLS. STORE THE ABS

ORBENT IN A CLOSED CONTAINER UNTIL
PROPERLY DISPOSED OF. PREVENT THE WASHINGS FROM ENTERING
WATERWAYS.

===== Handling and Storage =====

Handling and Storage Precautions:KEEP CONTAINER CLOSED WHEN NOT IN USE.
STORE IN A COOL, DRY AREA. STORE/USE ONLY W/ADEQUATE VENTILATION.
KEEP AWAY FROM IGNITION SOURCES.

Other Precautions:DON'T STORE IN EXCESSIVE HEAT TO PROLONG SHELF LIFE.
DON'T TAKE INTERNALLY. KEEP OUT OF CHILDRENS REACH. EMPTY
CONTAINERS CONTAIN HAZARDOUS RESIDUE. TRANSFER TO APPROVED
CONTAINERS W/COMPLETE LABELING . AVOID BREATHING OF VAPORS.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE A NIOSH APPROVED RESPIRATOR AS REQUIRED TO
PREVENT OVEREXPOSURE. USE EITHER A FULL FACE, ATMOSPHERE SUPPLYING
RESPIRATOR/AN AIR PURIFYING RESPIRATOR FOR ORGANIC VAPORS.

Ventilation:LOCAL EXHAUST PREFERABLE. GENERAL EXHAUST ACCEPTABLE IF
EXPOSURE IS MAINTAINED BELOW APPLICABLE LIMITS.

Protective Gloves:SOLVENT IMPERMEABLE

Eye Protection:SOLVENT RESISTANT SAFETY GLASSES

Other Protective Equipment:W/UNPERFORATED SIDESHIELD, BARRIER CREAMS,
SOLVENT IMPERMEABLE CLOTHING/APRONS/BOOTS/EYEWASH FOUNTAINS &
SAFETY SHOWERS.

Supplemental Safety and Health

===== Physical/Chemical Properties =====

Boiling Pt:B.P. Text:>212F

Vapor Density:>1

Spec Gravity:1.09

VOC Pounds/Gallon:170

pH:(SUPP)

Evaporation Rate & Reference:SLOWER THAN ETHER

Percent Volatiles by Volume:52.8

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

STRONG OXIDIZING AGENTS, STRONG LEWIS/MINERAL ACIDS, STRONG
MINERAL/ORGANIC BASES (PRIMARY/SECONDARY AMINES).

Stability Condition to Avoid:OPEN FLAMES, HIGH TEMPS & OTHER IGNITION
SOURCES

Hazardous Decomposition Products:HEATED: CO, ALDEHYDES, ACIDS & OTHER
ORGANIC COMPOUNDS.

===== Disposal Considerations =====

=====

Waste Disposal Methods:DISPOSE OF IAW/FEDERAL, STATE & LOCAL
REGULATIONS. INCINERATE MATERIAL ONLY IN AN APPROVED FACILITY.

===== Other Information =====

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaim
s all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.