View NSN Online: https://aerobasegroup.gr/nsn/3439-01-325-7642

Product ID:ARCAIR SLICE CUTTING ROD, UNCOATED (SUPPLEMENTAL) MSDS Date:01/01/1996 FSC:3439 NIIN:01-325-7642 MSDS Number: CBTHM === Responsible Party === Company Name: TWECO PRODUCTS INC Address:4200 W HARRY STREET Box:12250 **City:WICHITA** State:KS ZIP:67277 Country:US Info Phon e Num:316-942-1421 Emergency Phone Num:316-648-5129 Preparer's Name: DENNIS WILSON CAGE:89381 === Contractor Identification === Company Name: TWECO PRODUCTS, INC. Address:4200 WEST HARRY ST. Box:12250 City:WICHITA State:KS ZIP:67277 Country:US Phone:316-946-8308;316-942-1421 CAGE:89381

Ingred Name:MILD STEEL Fraction by Wt: 99%+ Other REC Limits:NONE RECOMMENDED

LD50 LC50 Mixture: NONE SPECIFIED BY MANUFACTURER. Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: INHAL: WHEN CUTTING CERTAIN MATLS(LEAD, CADMIUM, BERYLLIUM, ETC) AIRBORNE CONC MAY EXCEED TLV'S CAUSING DRYNESS OF THROAT, BREATHING DIFFICULTY OR UNCONSC.VISUAL: EXPO TO ULTRA-VIOLET RADIATION FROM POWDERED ARC CAN RESULT IN KERATONCONJUNCTIVITIS(WELDERS FLASH)CAUSING INFLAMM, BLURRED VISI ON, HEADACHE. Explanation of Carcinogenicity: PER MSDS: CARCINOGENICITY: NOT LISTED. Effects of Overexposure: DRYNESS OF THROAT, BREATING DIFFICULTY OR UNCOSNC. KERATONCONJUNCTIVITIS (WELDER'S FLASH) CAUSING INFLAMMATION, BLURRED VISION, HEADACHE. Medical Cond Aggravated by Exposure: POSSIBLY EXISTING RESPIRATORY.

First Aid:INHAL:REMOVE TO FRESH AIR & SEEK MED ATTN. VISUAL:CONSULT PHYSICIAN-PREFERABLY AN EYE SPECIALIST.

Flash Point:NA Autoignition Temp:Autoignition Temp Text:NA Lower Limits:NA Upper Limits:NA Extinguishing Media:DOES NOT BURN READILY. Fire Fighting Procedures:DOES NOT BURN READILY. Unusual Fire/Explosion Hazard:NONE.

Spill Release Procedures: PICK UP SPENT ENDS WHEN COOL. Neutralizing Agent: NONE SPECIFIED BY MANUFACTURER.

====== Handling a

===

Handling and Storage Precautions:STORE IN LOW HUMIDITY ENVIRONMENT.AVOID BREATHING VAPORS!INTENSE HEAT GENERATED WHEN IN OPERATION!

Other Precautions: WHEN PLACED INTO SERVICE W/WELDING POWER SOURCE, AN INTENSE ELCTRIC ARC IS CREATED GENERATING FUMES/GASES/ULTRA-VIOLET RAYS WHICH CAN DMG EYE/PENETRATE LIGHT CLOTH/BURN SKIN. WHEN NOT IN SERVICE RODS PO SE NO PARTICULAR HAZARD.

Respiratory Protection:NIOSH-MESA DETERIMINED FOR FUME/DUST PROTECTION. AS REQUIRED TO MAINTAIN BELOW TLV'S.

Ventilation:LOC EXHAUST:PREFERRED FOR FUME/DUST REDUCTION.

MECHANICAL: TO MAINTAIN BELOW TLV'S/PEL'S.

Protective Gloves: AS USED IN CONVENTIONAL ARC WELDING.

Eye Protection: FACESHIELD; FILTER LENS FOR UV PROTECTION

Other Protective Equipment: AS USED IN CONVENTIONAL ARC WELDING. SUITABLE FOOTWEAR FOR METAL WORKING.

Work Hygienic Practices: OPERATOR TRAINED TO AVOID ELECTRICAL SHOC K & UV

RAY EXPOSURE.

Supplemental Safety and Health CAT #:43-079-002,-003,-007,-009,-005.

HCC:N1 Boiling Pt:B.P. Text:NA Melt/Freeze Pt:M.P/F.P Text:NA Decomp Temp:Decomp Text:NP Vapor Pres:NA Vapor Density:NA Spec Gravity:NA pH:NA Viscosity:NP Evaporation Rate & amp; Reference:NA Solubility in Water:INSOLUBLE. Appearance and Odor:SOLID, ROLLED STEEL TUBE, NO NOTABLE ODOR. Percent Volatiles by Volume:NP Corrosion Rate:NP Stability Indicator/Materials to Avoid:YES NONE KNOWN.

Hazardous Decomposition Products: IRON OXIDE FUMES IN ADDITION TO THOSE GENERATED BY MATERIALS BEING CUT.

Waste Disposal Methods: SOLID LANDFILL IF LOCAL REGULATIONS ALLOW.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and

disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and

assume responsibility for the suitability of this information to their particular situation.