View NSN Online: https://aerobasegroup.gr/nsn/5960-00-248-1270

COMMUNICATIONS AND POWER INDUSTRIES INC -- 5922 -- 5960-00-248-1270

Product ID:5922

MSDS Date:08/31/1998

FSC:5960

NIIN:00-248-1270

Status Code:A

Article:Y

MSDS Number: CJKMM === Responsible Party ===

Company Name: COMMUNICATIONS AND POWER INDUSTRIES INC

Address:150 SOHIER RD

City:BEVERLY

State:MA

ZIP:01915-5595

Country:US

Info Phone Num:978-922-6000 EXT.285

Emerg

ency Phone Num:978-922-6000 Preparer's Name:FRANK E. TROJAN

CAGE:88236

=== Contractor Identification ===

Company Name: COMMUNICATIONS AND POWER INDUSTRIES INC

Address:150 SOHIER RD

City:BEVERLY

State:MA

ZIP:01915-5595

Country:US

Phone:978-922-6000 EXT.285 Contract Num:SP0960-98-X-3053

CAGE:88236

====== Composition/Information on Ingredients ========

Ingred Name: COBALT-60

CAS:10198-40-0

Routes of Entry: Inhalat

ion:YES Skin:YES Ingestion:NO

Health Hazards Acute and Chronic:TARGET ORGANS: RESPIRATORY SYSTEM, SKIN, BLADDER, KIDNEYS, & EYES. ACUTE- SKIN: MAY RESULT IN BURNS. CONTACT DERMATITIS. RAPID ESTIMATION OF THE AMOUNT OF INTERNAL CONTAMINATION IS DIFFICULT OR IMPOS SIBLE WHEN ALPHA OR PURE BETA EMITTERS ARE INVOLVED. INHALATION: BREATHING DIFFICULTIES. CHRONIC- ALLERGIC ASTHMA, RESTRICTED PULMONARY FUNCTIONS, AND INTERNAL FIBROSIS MAY BE CAUSED BY LONG-TERM OC CUPATIONA

L EXPOSURE

TO COBALT AND ITS COMPOUNDS.

Explanation of Carcinogenicity: CANCER CAUSING AGENT: BETA OR GAMMA RAYS

Effects of Overexposure:NAUSEA & VOMITING & DIARRHEA FOR HIGH ACUTE DOSES. INHALATION OF COBALT DUST CAN CAUSE PULMONARY SYMPTOMS SUCH AS WHEEZING, IRRITATION OF THE UPPER RESPIRATORY TRACT & HYPERSENSITIVITY REACTIONS (AST HMA). SKIN CONTACT W/ POWDERED COBALT MAY CAUSE ADENITIDES, ESPECIALLY IN THE CREASES OF THE ELBOWS, KNEES, ANKLES, & NECK. CONTACT W

ITH EYES MAY CAUSE

CONJUNCTIVITIS. INGESTION MAY PRODUCE A HOT SE NSATION ALONG WITH VOMITING, DIARRHEA, & NAUSEA.

Medical Cond Aggravated by Exposure: HEALING OF DAMAGED TISSUES MAY BE PROLONGED. DISORDERS OF THE SKIN & THE UPPER RESPIRATORY TRACT MAY BE WORSENED BY EXPOSURE TO COBALT.

First Aid:EYES: IMMEDIATELY FLUSH EYES, INCLUDING UNDER THE EYELIDS, GENTLY BUT THOROUGHLY WITH PLENTY OF RUNNING WATER F OR AT LEAST 15

MIN. SKIN: IMMEDIATELY WASH THE AFFECTED AREA WITH SOAP AND WATER. INHAL ATION: REMOVE THE EXPOSED PERSON TO FRESH AIR, RESTORE AND/OR SUPPORT HIS OR HER BREATHING AS NEEDED. INGESTION: NEVER GIVE ANYTHING BY MOUTH TO SOMEONE WHO IS UNCONSCIOUS OR CONVULSING. IF COBALT SA LTS ARE INGESTED, GIVE ONE TO TWO GLASSES OF WATER & INDUCE VOMITING.

======== Accidental Release Measures ===========

Spill Release Procedures: WHEN HANDLING BROKEN

TUBES WEAR PROTECTIVE
RUBBER GLOVES & CLOTHING. AVOID THE POSSIBILITY OF RUBBING
RADIOACTIVE MATERIAL ONTO THE SKIN. WASH EXPOSED SKIN AFTER
HANDLING BROKEN TUBES CONTAINING RADIO ACTIVE MATERIALS.
======================================
Handling and Storage Precautions:ELECTRON TUBES SHOULD BE STORED IN A
CLEAN DRY ENVIRONMENT SUITABLE FOR ELECTRONIC EQUIPMENT. TUBES WITH
PERMANENT MAGNETS MAY GENERATE STRAY MAGNETIC FIELDS.
======= Exp
osure Controls/Personal Protection =========
Work Hygienic Practices:WASH HANDS.
Supplemental Safety and Health
THIS DEVICE IS A RECEIVER PROTECTOR TUBE WHICH CONTAINS A SMALL AMOUNT
OF COBALT 60. THE TUBE IS CONSIDERED TO BE A SEALED SOURCE & NORMAL
HANDLING WILL PRESENT NO RADIATION PROBLEMS. THIS DEVICE IS A
MANUFACTURED ARTICLE IN ACCORDANCE WITH 49 CFR 173.422. THIS DEVICE

========= Physical/Chemical Proper ties =========

IS AN ARTICLE IN ACCORDANCE WITH 29 CFR 1910.1200.

HCC:A3
Boiling Pt:=2900.C, 5252.F
Melt/Freeze Pt:=1495.C, #####F
Vapor Pres: