Product ID:PAINT DARK BROWN 412-0115 L115 6AHK33474 MSDS Date:09/01/1992 FSC:8010 NIIN:01-344-5119 Status Code:A MSDS Number: CLJGK === Responsible Party === Company Name: AKZO COATINGS Address:1845 MAXWELL STREET City:TROY State:MI ZIP:48084 Country:US Info Phone Num:313-637-0400 Emerg ency Phone Num: (800) 424-9300 Preparer's Name: HENRY SIMMONS Chemtrec Ind/Phone:(800)424-9300 CAGE:2E800 === Contractor Identification === Company Name: AKZO COATINGS Address:1845 MAXWELL STREET Box:City:TROY State:MI ZIP:48084 Country:US Phone:313-637-0400 CAGE:2E800

Ingred Name:ALIPHATIC HYDROCARBON SOLVENT CAS:64741-41-9 &It; Wt:5. OSHA PEL:500 PPM

Ingred Name:IRON OXIDE RED CAS:1309-37-1 RTECS #:NO7400000 Minumum % Wt:5. Ma xumum % Wt:20. OSHA PEL:10 MG/M3 ACGIH TLV:5 MG/M3;2 PPM

Ingred Name:CARBON BLACK CAS:1333-86-4 RTECS #:FF5800000 Minumum % Wt:5. Maxumum % Wt:20. OSHA PEL:3.5 MG/M3 ACGIH TLV:3.5 MG/M3

Ingred Name:LIGHT PETROLEUM DISTILLATE CAS:64742-47-8 RTECS #:OA5504000 Minumum % Wt:5. Maxumum % Wt:20. OSHA PEL:400 PPM, 1600 MG/M3

Ingred Name:STODDARD SOLVENT CAS:8052-41-3 RTECS #:WJ8925000 Minumum % Wt:25. Maxumum % Wt:40. OSHA PEL:2900 MG/M3;500 PPM ACGIH TLV:525 MG/M3;100 PPM

======= На

Health Hazards Acute and Chronic:ACUTE: 1. EXCESSIVE VAPOR CONCENTRATION IN AIR, ESPECIALLY IN CONFINED SPACES, MAY CAUSE ASPHYXIATION. 2. EXCESSIVE INHALATION OF VAPORS CAN CAUSE NASAL, THROAT, AND RESPIRATORY IRRITATION, DIZZINESS, WEAKNESS, FATIGUE, NAUSEA, HEADACHE AND POSSIBLE UNCONCIOUSNESS. 3. SANDING DUST OR DRY SPRAY MAY CAUSE IRRITATION TO THE RESPIRATORY SYSTEM. 4. EYE CONTACT WITH LIQUID, VAPOR OR SPRAY MIST CAUSES IR RITATION,

REDNESS, TEARING, BLURRED VISION, AND A SENSATION OF SEEING HALOS AROUND LIGHTS. 5. DRY DUST MAY CAUSE MECHANICAL EYE IRRITATION. 6. PROLONGED SKIN CONTACT MAY LEAD TO EXTRATION OF NATURAL O ILS WITH RESULTANT DRY SKIN, CRACKING.

Medical Cond Aggravated by Exposure:NONE EXPECTED.

First Aid:INHALATION: MOVE TO FRESH AIR, GIVE ARTIFICIAL RESPIRATION IF NECESSARY. SKIN CONTACT: WASH WITH SOAP AN

D WATER. DO NOT ORGANIC SOLVENTS. EYE CONTACT: FLUSH WITH WATER FOR AT LEAST 15 MINUTES. CONSU LT A PHYSICIAN. INGESTION: DRINK ONE OR TWO GLASSES OF WATER TO DILUTE. DO NOT INDUCE VOMITING. CONSULT A PHYSICIAN OR POISON CONTROL CENTER IMMEDIATELY. TREAT SYMPTOMATICALLY. Flash Point:=40.6C, 105.F Lower Limits:0.6 Extinguishing Media: FOAM, CARBON DIOXIDE, DRY CHEMICALS ARE DESIRABLE. WATER SPRAY IS LESS E FFECTIVE. Fire Fighting Procedures:WATER SHOULD BE USED TO COOL CONTAINERS EXPOSED TO FIRE. FIRE FIGHTING PERSONNEL SHOULD WEAR SELF-CONTAINING BREATHING APPARATUS. Unusual Fire/Explosion Hazard: KEEP CONTAINERS TIGHTLY CLOSED, ISOLATE FROM HEAT, ELECTRICAL EQUIPMENT, SPARKS, AND OPEN FLAME. CLOSED CONTAINERS MAY EXPLODE WHEN EXPLODE WHEN EXPOSED TO EXTREME HEAT. APPLICATION TO HOT SURFACES RE QUIRES SPECIAL PRECAUTIONS. ======= Accidental Release Measures ====== _____ Spill Release Procedures: REMOVE ALL SOURCES OF IGNITION. AVOID BREATHING VAPORS, VENTILATE AREA, REMOVE WITH INERT ABSORBENT USING NON-SPARKING TOOLS. Handling and Storage Precautions: STORE CONTAINERS OUT OF SUN AND AWAY FROM HEAT, SPARKS AND OPEN FLAMES. STORE PLASTIC CONTAINERS OF FLAMMABLE LIQUIDS INSIDE CLOSED, APPROVED CONTAINERS OR SAFETY CABINETS. CLOSE ALL CONTAINERS AFTER EACH USE. C **ONSULT NFPA AND** LOCAL CODES FOR ADDITIONAL STORAGE REQUIREMENTS. Other Precautions: DO NOT TAKE INTERNALLY. USE APPROVED BONDING AND

GROUNDING PROCEDURE WHEN TRANSFERRING LIQUIDS. OBSERVE LABEL PRECAUTIONS. KEEP CLOSURES TIGHT AND CONTAINER UPRIGHT TO PREVENT LEAKAGE. NEVER USE PRESS URE TO EMPTY CONTAINER ? DRUM IS NOT A PRESSURE VESSEL. AVOID BREATHING SANDING DUST. DO NOT WELD OR FLAME CUT.

======= Exposure Controls/Personal Protection ==========

Respirato

- ry Protection:ADEQUATE VENTILATION IS REQUIRED. USE NIOSH/MSHS APPROVES RESPIRATOR DEVICE. SEE YOUR SAFETY EQUIPMENT SUPPLIER FOR EVALUATION AND RECOMMENDATION. IN CONFINED AREAS USE NIOSH/MSHA APPROVED AIRLINE RES PIRATOR OR HOOD.
- Ventilation: PROVIDE SUFFICIENT VENTILATION TO KEEP VAPOR CONCENTRATION BELOW THE GIVEN TLV AND PEL.

Protective Gloves: REQUIRED FOR PROLONGED OR REPEATED CONTACT. Eye Protection: USE SAFETY EYE GOGGLES DESIGNED TO PROTECT AGAINST SPLASH OF LIQUIDS.

0

- ther Protective Equipment:EYE AND BATH SHOWER SHOULD BE AVAILABLE. USE CHEMICAL RESISTANT APRON, BOOTS OR OTHER CLOTHING IF NEEDED TO AVOID REPEATED OR FREQUENT SKIN CONTACT. LIQUID MAY PENETRATE CLOTHING, SHOES AND LEATHER.
- Work Hygienic Practices: WASH HANDS BEFORE EATING, SMOKING, OR USING THE WASHROOM, LAUNDER CLOTHING BEFORE REUSE.
- Supplemental Safety and Health

Boiling Pt:=148.9C, 300.F B.P. Text:300-490F

Spec Gravity:1.04 Percent Volatiles by Volume:53

Stability Indicator/Materials to Avoid:YES NONE REASONABLY FORESEEABLE Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOXIDE, OXIDES OF NITROGEN AND SMOKE.

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH FEDERAL, STATE, AND LOCAL POLLUTION REQUIREMENTS RAGS, FILTERS, PAINT SUITS, EMPTY

CANS, ETC., CONTAMINATED WITH PRODUCT MAY BE HAZARDOUS WASTE. DETERMINE WHETHER CONTAMI NATED PRODUCTS ARE HAZARDOUS BEFORE DISPOSAL AND DISPOSE OF AS APPROPRIATE.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any p

erson utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.