## NSN 1075-01-315-0764

Repairability:

Stub Ramp Floor Installation - Page 1 of 1



When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.