NSN 2835-01-083-2975

Repairability:

Nonaircraft Gas Turbine Engine Turbine Shaft - Page 1 of 1



View Online at https://aerobasegroup	.gr/nsn/2835-01-083-2975
--------------------------------------	--------------------------

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.