## NSN 6105-00-635-2861

Motor Rotor - Page 1 of 1



View Online at https://aerobasegroup.gr/nsn/6105-00-635-2861

## 

Hazmat:

No

:

## Repairability:

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.