NSN 2995-01-314-4302

Repairability:

Gas Turbine Engine History Recorder - Page 1 of 1



View Online at https://aerobasegroup.gr/nsn/2995-01-314-4302
:
:
Shelf Life:
N/a
Unit Of Measure:
1 ea
Demilitarization:
Yes - demil/mli
Fiig:
A23900
Hazmat:
No

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.