NSN 5895-01-111-0078

Radio Receiver - Page 1 of 1



View Online at https://aerobasegroup.gr/nsn/5895-01-111-0078

Hazmat:

No

:

Repairability:

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.